

AD-A085 227

GAI CONSULTANTS INC MONROEVILLE PA

F/6 13/13

NATIONAL DAM INSPECTION REPORT. LEBANON RESERVOIR DAM NUMBER 1.--ETC(U)

MAR 80 B M MIHALCIN

DACW311-80-C-0016


NL


UNCLASSIFIED

1 of 2

AD-A085 227

AD-A085 227





MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

ADA 085227

SUSQUEHANNA RIVER BASIN  
WEST BRANCH OF HAMMER CREEK, LEBANON COUNTY


⑥ National Dam Inspection Report  
PENNSYLVANIA

LEBANON RESERVOIR DAM No. 1

Number  
NDI ID. PA-00595,  
PENNDER ID. No. 38-1.

Susquehanna River Basin, West Branch of  
Hammer Creek, Lebanon County, Pennsylvania.  
PHASE I INSPECTION REPORT,  
NATIONAL DAM INSPECTION PROGRAM

⑫ 117



JUN 6 1980

PREPARED FOR  
DEPARTMENT OF THE ARMY  
Baltimore District, Corps of Engineers  
Baltimore, Maryland 21203

⑮ DACV131-44-C-0014

PREPARED BY

GAI CONSULTANTS, INC.  
570 BEATTY ROAD  
MONROEVILLE, PENNSYLVANIA 15146

⑪ MARCH 1980

This document has been approved  
for public release and sale; its  
distribution is unlimited.

ORIGINAL CONTAINS COLOR PLATES: ALL DDG  
REPRODUCTIONS WILL BE IN BLACK AND WHITE.

WUG FILE WELL

GAI CONSULTANTS, INC.  
DACW31-80-C-0016

80 6 6 411002 049

JUC

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D. C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The spillway design flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition, and the downstream damage potential.

This report has been approved  
for publication and sale; its  
distribution is unlimited.

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

ABSTRACT

Lebanon Reservoir Dam No. 1: NDI I.D. No. PA-00595

Owner: City of Lebanon  
State Located: Pennsylvania (PennDER I.D. No. 38-1)  
County Located: Lebanon  
Stream: West Branch of Hammer Creek  
Inspection Date: 8 November 1979  
Inspection Team: GAI Consultants, Inc.  
570 Beatty Road  
Monroeville, Pennsylvania 15146

↓  
The visual inspection, operational history, and hydrologic/hydraulic analysis indicate that the facility is in fair condition.

Deficiencies noted by the inspection team included heavy overgrowth across the embankment crest and slopes, rodent burrows along the downstream embankment face, a deteriorated emergency spillway, and minor seepage beneath the emergency spillway and around the outlet conduit. These deficiencies are, for the most part, attributable to a general lack of adequate maintenance since the facility was phased out of operation in 1973.

↘ The size classification of the facility is small and its hazard classification is considered to be high. In accordance with the recommended guidelines, the Spillway Design Flood (SDF) for the facility ranges between the 1/2 PMF (Probable Maximum Flood) and the PMF. Due to the high potential for damage to downstream structures and loss of life, the SDF is considered to be the PMF. Results of the hydrologic and hydraulic analysis indicate the facility will pass and/or store only 16 percent of the PMF prior to embankment overtopping. A breach analysis indicates that failure under less than 1/2 PMF conditions could lead to increased downstream damage and potential for loss of life. Thus, based on screening criteria provided in the recommended guidelines, the spillway is considered to be seriously inadequate and the facility unsafe, non-emergency.

It is recommended that the owner immediately:


- a. Develop a formal emergency warning system to notify downstream residents should hazardous conditions develop. Included in the plan should be provisions for around-the-clock surveillance of the facility during periods of unusually heavy precipitation.
- b. Have the facility evaluated by a registered professional engineer experienced in hydrology and hydraulic structures and take remedial measures deemed necessary to make the facility hydraulically adequate and the emergency spillway structurally sound.
- c. Clear all excess vegetation from the embankment crest and slopes. In addition, all burrowing animals inhabiting the embankment should be exterminated and their burrows filled.
- d. Develop formal manuals of operation and maintenance to ensure future proper care of the facility.
- e. Specifically address in all future inspections the seepage conditions beneath the emergency spillway and around the outlet conduit at the downstream embankment toe noting changes in turbidity and/or rate of flow.
- f. Provide upstream (inlet end) control of flow through the outlet conduit or develop a plan to control flow through the conduit at the inlet end in the event emergency conditions develop in the pipe within the embankment.

GAI Consultants, Inc.

Approved by:

*Bernard M. Mihalcin*  
Bernard M. Mihalcin, P.E.

*James W. Peck*  
JAMES W. PECK  
Colonel, Corps of Engineers  
District Engineer



Date 27 March 1980  
DLB:BMM/lc

Date 3 May 1980



Downstream Face



Upstream Face

OVERVIEW PHOTOGRAPHS

## TABLE OF CONTENTS

|   | <u>Page</u> |
|---|-------------|
| PREFACE . . . . .   | i           |
| ABSTRACT. . . . .   | ii          |
| OVERVIEW PHOTOGRAPHS. . . . .   | iv          |
| TABLE OF CONTENTS . . . . .   | v           |
| SECTION 1 - GENERAL INFORMATION . . . . .                                     | 1           |
| 1.0 Authority . . . . .   | 1           |
| 1.1 Purpose . . . . .   | 1           |
| 1.2 Description of Project. . . . .   | 1           |
| 1.3 Pertinent Data. . . . .   | 2           |
| SECTION 2 - ENGINEERING DATA. . . . .   | 6           |
| 2.1 Design. . . . .   | 6           |
| 2.2 Construction Records. . . . .   | 7           |
| 2.3 Operational Records . . . . .   | 7           |
| 2.4 Other Investigations. . . . .   | 8           |
| 2.5 Evaluation. . . . .   | 8           |
| SECTION 3 - VISUAL INSPECTION . . . . .                                       | 9           |
| 3.1 Observations. . . . .   | 9           |
| 3.2 Evaluation. . . . .   | 10          |
| SECTION 4 - OPERATIONAL PROCEDURES. . . . .                                   | 11          |
| 4.1 Normal Operating Procedure. . . . .                                       | 11          |
| 4.2 Maintenance of Dam. . . . .   | 11          |
| 4.3 Maintenance of Operating Facilities . . . . .                             | 11          |
| 4.4 Warning System. . . . .   | 11          |
| 4.5 Evaluation. . . . .   | 11          |
| SECTION 5 - HYDROLOGIC/HYDRAULIC EVALUATION . . . . .                         | 12          |
| 5.1 Design Data . . . . .   | 12          |
| 5.2 Experience Data . . . . .   | 12          |
| 5.3 Visual Observations . . . . .   | 12          |
| 5.4 Method of Analysis. . . . .   | 12          |
| 5.5 Summary of Analysis . . . . .   | 12          |
| 5.6 Spillway Adequacy . . . . .   | 16          |
| SECTION 6 - EVALUATION OF STRUCTURAL INTEGRITY. . . . .                       | 17          |
| 6.1 Visual Observations . . . . .   | 17          |
| 6.2 Design and Construction Techniques. . . . .                               | 17          |
| 6.3 Past Performance. . . . .   | 17          |
| 6.4 Seismic Stability . . . . .   | 18          |
| SECTION 7 - ASSESSMENT AND RECOMMENDATIONS FOR<br>REMEDIAL MEASURES . . . . . | 19          |
| 7.1 Dam Assessment. . . . .   | 19          |
| 7.2 Recommendations/Remedial Measures . . . . .                               | 19          |



## TABLE OF CONTENTS

|   |
|---|
| APPENDIX A - VISUAL INSPECTION CHECKLIST AND FIELD SKETCHES |
| APPENDIX B - ENGINEERING DATA CHECKLIST                     |
| APPENDIX C - PHOTOGRAPHS                                    |
| APPENDIX D - HYDROLOGY AND HYDRAULICS ANALYSES              |
| APPENDIX E - FIGURES  |
| APPENDIX F - GEOLOGY  |

|  |                |
|--|----------------|
| Accession For                                  |                |
| NTIS GRA&I <input checked="" type="checkbox"/> |                |
| DDC TAB <input type="checkbox"/>               |                |
| Unannounced <input type="checkbox"/>           |                |
| Justification <i>Per ltr</i>                   |                |
| <i>on file</i>                                 |                |
| By <i>[Signature]</i>                          |                |
| Distribution/                                  |                |
| Availability                                   |                |
| Dist   | Availability   |
| <i>A</i>                                       | <i>Special</i> |

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM  
LEBANON RESERVOIR DAM NO. 1  
NDI# PA-00595, PENNDER# 38-1

SECTION 1  
GENERAL INFORMATION

1.0 Authority.

The Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of inspection of dams throughout the United States.

1.1 Purpose.

The purpose is to determine if the dam constitutes a hazard to human life or property.

1.2 Description of Project.

a. Dam and Appurtenances. Lebanon Reservoir Dam No. 1 is an earth embankment approximately 30 feet high and 700 feet long, including spillways. The facility is provided with separate service and emergency spillways located at the right abutment. The combined spillway crest length is approximately 48 feet. The facility is equipped with a 16-inch diameter cast iron blowoff conduit located about 300 feet to the left of the spillways. The blowoff is controlled by a 16-inch diameter gate valve located at about the middle of the downstream embankment slope. The facility is also equipped with system of water supply conduits that were phased out of operation in the early 1970's.

b. Location. Lebanon Reservoir Dam No. 1 is located on the West Branch of Hammer Creek in South Lebanon Township, Lebanon County, Pennsylvania. The City of Lebanon, Pennsylvania, is located about 6 miles northwest of the facility. The dam, reservoir, and watershed are contained within the Richland and Lebanon, Pennsylvania 7.5 minute U.S.G.S. topographic quadrangles (see Figure 1, Appendix E). The coordinates of the dam are N40° 16.8' and W76° 21.5'.

c. Size Classification. Small (30 feet high; 82 acre-feet storage capacity at top of dam).

d. Hazard Classification. High (see Section 3.1.e).

e. Ownership. City of Lebanon.  
400 South 8th Street  
Lebanon, Pennsylvania 17042

f. Purpose. Recreation and emergency water supply.

g. Historical Data. Lebanon Reservoir Dam No. 1 was constructed under private contract to supply both domestic and industrial water for the City of Lebanon in 1871. The original facility was designed by H.P.M. Birkinbine of Philadelphia. Dam No. 1 was one of three similar earth structures located on the West Branch of Hammer Creek in South Lebanon Township. Lebanon Reservoir Dam No. 2 still exists and is located several hundred feet upstream of Dam No. 1. Lebanon Reservoir Dam No. 3 was located about 2000 feet upstream on a small creek in an adjacent watershed to the west of Dam No. 2. Discharge from Dam No. 3 was, however, directed into Dam No. 1.

According to information contained in files obtained from PennDER, Dam No. 3 failed as a result of heavy rainfalls that occurred on July 25, 1925. The combination of the failure of Dam No. 3 (which was never restored) and the heavy runoff from its own watershed resulted in the overtopping and subsequent failure of Dam No. 1. Dam No. 2 reportedly incurred damage due to the heavy rainfall, but, was not overtopped and remained essentially intact. Failure of Dam No. 1 resulted in a breach to the left of the gate house measuring 75 feet across the top and 30 to 35 feet along the base which was subsequently repaired. No casualties were reported resulting from this incident.

Following reconstruction, yearly inspection reports by PennDER predecessors indicate a serious seepage condition along the downstream toe. This condition was adequately controlled in 1938 when the downstream slope was flattened and internal drainage was provided.

Lebanon Reservoir Dam No. 1 along with upstream Dam No. 2 were phased out of active operation in 1973. Both facilities are now used for recreation and emergency water supply only.

### 1.3 Pertinent Data.

|   |             |
|---|-------------|
| a. <u>Drainage Area (square miles).</u> | 0.6 (local) |
|   | 1.2 (total) |

b. Discharge at Dam Site.

Discharge Capacity of Outlet Conduit - Discharge curves are not available.

Discharge Capacity of Service Spillway at Maximum Pool = 130 cfs (see Appendix D, Sheet 7).

Discharge Capacity of Emergency Spillway at Maximum Pool = 340 cfs (see Appendix D, Sheet 8).

c. Elevation (feet above mean sea level). The following elevations were obtained from available drawings and through field measurements that were based on the elevation of the service spillway crest or normal pool at 622.5 feet (see Appendix D, Sheet 1).

|                             |                                   |
|-----------------------------|-----------------------------------|
| Top of Dam                  | 626.0 (design).<br>625.3 (field). |
| Maximum Design Pool         | Not known.                        |
| Maximum Pool of Record      | Not known.                        |
| Normal Pool                 | 622.5                             |
| Service Spillway Crest      | 622.5                             |
| Emergency Spillway Crest    | 623.0                             |
| Upstream Inlet Invert       | 603.0 (estimated zero storage).   |
| Downstream Outlet Invert    | 594.9                             |
| Streambed at Dam Centerline | 598.0                             |
| Maximum Tailwater           | Not known.                        |

d. Reservoir Length (feet).

|             |     |
|-------------|-----|
| Top of Dam  | 600 |
| Normal Pool | 450 |

e. Storage (acre-feet).

|                  |            |
|------------------|------------|
| Top of Dam       | 82         |
| Normal Pool      | 55         |
| Design Surcharge | Not known. |

f. Reservoir Surface (acres).

|                     |            |
|---------------------|------------|
| Top of Dam          | 9          |
| Normal Pool         | 11         |
| Maximum Design Pool | Not known. |

g. Dam.

|      |        |
|------|--------|
| Type | Earth. |
|------|--------|

|   |  |
|---|--|
| Length  | 700 feet (including spillways).  |
| Height  | 30 feet (field measured; crest to downstream blowoff invert).  |
| Top Width   | 12 feet.   |
| Upstream Slope                                    | 1.5H:1V (field measured; above normal pool).<br>2H:1V (below normal pool; see Figures 3 and 4).  |
| Downstream  | 3H:1V.   |
| Zoning  | Early correspondence indicates the inner half of the embankment was composed of "selected material" while the outer half was composed of "earth and stone." Internal drainage was provided during subsequent reconstruction. |
| Impervious Core                                   | None indicated. See above.   |
| Cutoff  | Partial concrete cutoff in former breach area (see Section 2.1.b.1).   |
| Grout Curtain                                     | None indicated.  |
| h. <u>Diversion Canal and Regulating Tunnels.</u> | None.  |
| i. <u>Service Spillway.</u>                       |  |
| Type  | Uncontrolled, rectangular, concrete chute channel with masonry   |

|    |                                   |   |
|----|-----------------------------------|---|
|    |                                   | wingwalls and a concrete sill crest.  |
|    | Crest Elevation                   | 622.5 feet.   |
|    | Crest Length                      | 10.5 feet.  |
| j. | <u>Emergency Spillway.</u>        |   |
|    | Type                              | Uncontrolled, rectangular, concrete chute channel with a broad crest.   |
|    | Crest Elevation                   | 623.0 feet.   |
|    | Crest Length                      | 37.8 feet.  |
| k. | <u>Outlet Conduit.</u>            |   |
|    | Type                              | 16-inch diameter cast iron blowoff conduit.   |
|    | Length                            | 80 feet (estimated).  |
|    | Closure and Regulating Facilities | Flow through the outlet conduit can be regulated by a 16-inch diameter gate valve with controls located about midway along the downstream embankment slope to the right (looking downstream) of concrete valve chamber situated at the downstream embankment toe. |
|    | Access                            | The outlet conduit control mechanism is housed in a curb box accessible by foot along the downstream embankment slope.  |

## SECTION 2 ENGINEERING DATA

### 2.1 Design.

a. Design Data Availability and Sources. No formal design reports or calculations are available for any aspect of the facility. Several drawings are available from both the owner and the PennDER (see Figures 2 through 4, Appendix E). A historical report contained in PennDER files entitled "Report Upon Dam No. 1 of the Lebanon City Water Works" by the Water Supply Commission of Pennsylvania, dated December 14, 1914, contains useful descriptive information relative to the design and construction of the facility.

b. Design Features.

1. Embankment. Little information is available relative to the physical characteristics of the embankment. Data contained in PennDER files indicates that the inner half of the embankment was to be made up of selected material while the outer half was to be composed of earth and stone. Available drawings indicate the embankment was originally 15 feet wide at the crest with 2H:1V slopes both upstream and downstream (see Figure 3).

In 1925, the dam was overtopped and subsequently breached. The breach, which began at a point 10 to 15 feet left of the gate house, measured about 75 feet long across the crest and 30 to 35 feet long across the base. In addition, the downstream slope was badly eroded for about 100 feet on either side of the breach.

Repairs to the damaged area were initiated immediately. Included was the placement of a concrete cutoff wall, 5 feet high and 18 inches thick, extending below the bottom of the breach and into the material remaining in place at the ends. The breach was refilled with puddle clay placed in 6-inch layers (see Figure 3).

Remedial work was again necessitated in 1938 in an effort to alleviate seepage along the downstream embankment toe. Additional material (including a rock drain) was reportedly added to the downstream slope and crest in accordance with the details shown on Figure 4. Six-inch diameter drains were placed along the toe of the former slope and discharge into a rock-lined ditch at the base of the present slope (see Photograph 10).

## 2. Appurtenant Structures.

a) Service Spillway. The service spillway is an uncontrolled, rectangular, concrete chute channel with masonry wingwalls located near the right abutment and to the right of the emergency spillway (see Figure 4 and Photographs 1 and 3). The crest consists of a small concrete sill 10.5 feet in length.

b) Emergency Spillway. The emergency spillway is an uncontrolled, rectangular, concrete chute channel located adjacent to the left wingwall of the service spillway near the right abutment (see Figure 4 and Photographs 1 and 2). The structure was constructed in 1925, subsequent to the flood which caused the embankment to overtop and fail. The crest is divided into two bays by a concrete pier that supports the remnants of a footbridge that once spanned both spillways. The effective crest length (minus the concrete pier) measures 37.8 feet.

c) Outlet Conduit. The blowoff conduit is a 16-inch diameter cast iron pipe with inlet located approximately 300 feet to the left of the service spillway (see Figure 3). The conduit discharges at the downstream embankment toe just beyond a concrete valve chamber that houses one of two 16-inch diameter gate valves located along the pipe (see Figures 3 and Photographs 6 and 7). The valve within the chamber is reportedly inoperable; however, control is provided by a second valve situated just upstream which is operated from a curb box located midway along the downstream embankment slope (see Photograph 8).

c. Specific Design Data and Criteria. No formal design reports, calculations, or specific design data are available for any aspect of this facility.

### 2.2 Construction Records.

No records are available for any phase of the facility's original construction in 1871. Information relative to the 1925 reconstruction and 1938 renovation is limited to brief reports and several photographs by the Water Supply Commission which are contained in PennDER files.

### 2.3 Operational Records.

No records of daily rainfall or spillway discharge are available. The events leading to the failure of the embankment in 1925 are well documented in PennDER files.



#### 2.4 Other Investigations.

No records of any formal investigations other than periodic state inspection reports are available. The inspection reports are contained in PennDER files.

#### 2.5 Evaluation.

The available data are considered sufficient to make a reasonable Phase I assessment of the facility.

SECTION 3  
VISUAL INSPECTION

3.1 Observations.

a. General. The general appearance of the facility suggests that it is in fair condition.

b. Embankment. Based on observations made during the visual inspection, the embankment is considered to be in fair condition. No evidence of seepage through the downstream embankment face or signs of slope distress were observed. The entire embankment, however, is heavily overgrown and lacks adequate maintenance (see Overview Photographs). At least two small rodent burrows were encountered along the downstream embankment face near the chlorination house. The riprap provided across the upstream embankment face is patchy; however, no evidence of significant erosion was observed.

c. Appurtenant Structures.

1. Service Spillway. The service spillway (see Photograph 3) is considered to be in good condition. No evidence of concrete or masonry deterioration was observed.

2. Emergency Spillway. The visual inspection revealed the emergency spillway is in poor condition (see Photographs 1 and 2). The concrete channel floor is severely scaled and cracked. Some slab uplifting and movement is apparent as is minor seepage through cracks and joints in the lower portion of the channel. The lower channel is overgrown with high grass and shrubs which have rooted themselves between the open cracks and joints (see Photographs 3 and 4).

The remnants of a steel supported footbridge span both the service and emergency spillways. Only the steel frame remains while all planking has been removed (see Photographs 2 and 3).

3. Outlet Conduit. The outlet conduit is reportedly functional; however, it was not operated in the presence of the inspection team. The concrete valve chamber located at the downstream embankment toe appears to be in good condition (see Photographs 6 and 7). The steel access doors atop the chamber are unhinged making the structure somewhat hazardous and susceptible to vandalism. The valve housed within the chamber is reportedly inoperable. Flow

through the conduit is controlled by a valve located about midway along the downstream slope and to the right (looking downstream) of the chamber. Operation of the upstream valve is provided through a curb box opening (see Photograph 8). Some minor seepage ( $\approx$  2 gpm) was observed around the conduit at the base of the chamber.

d. Reservoir Area. Lebanon Reservoir Dam No. 1 is situated along the southern edge of a heavily forested, steeply sloped area known as South Mountain. The northern, eastern and western flanks of the reservoir are comprised of gently to moderately sloped farmland (see Figure 1). No evidence of slope distress was observed in the general area surrounding the reservoir.

e. Downstream Channel. Low flows through the service spillway are channeled as indicated by the thin blue line shown on Figure 1. That is, flows are directed into a small farm pond to the right of the embankment prior to joining the natural stream channel near Pennsylvania Route 419 several hundred feet downstream. A diversion channel cut roughly parallel to the embankment, approximately 150 feet downstream of the service spillway crest, diverts large flows from the service spillway into the original stream channel below the outlet conduit (see General Plan-Field Inspection Notes, Appendix A). Emergency spillway and outlet conduit flows are discharged directly into the original stream channel which is depicted on Figure 1 by a dotted line.

Approximately 2700 feet downstream the original stream channel passes within 100 feet of a structure referred to as "Kralls Church" on Figure 1. This structure is now a private residence. A brief discussion with the owner of this residence revealed that his home experiences some high water almost annually. Due to the close proximity of this home to the stream, along with several other homes and farms further downstream, the hazard classification for this facility is considered to be high as an embankment failure could affect more than a few lives.

### 3.2 Evaluation.

Based on visual observations, the overall condition of the facility is considered to be fair. Heavy overgrowth and a deteriorated emergency spillway are primarily the result of inadequate maintenance. Seepage observed beneath the spillway and around the outlet conduit are considered minor at this time, but should continue to be assessed in future inspections.

## SECTION 4 OPERATIONAL PROCEDURES

### 4.1 Normal Operating Procedure.

The reservoir is presently used for recreation and emergency water supply only. It is not a regular part of the City of Lebanon's water supply system. The facility is essentially self-regulating. Excess inflows discharge through the spillways and are directed downstream. The outlet conduit and supply system are reportedly functional; however, no specific operating procedures exist and no formal operations manual is available.

### 4.2 Maintenance of Dam.

The facility has been virtually without maintenance since it was phased out of operation in 1973. The owner is capable of performing emergency maintenance if needed. No formal maintenance manual outlining any maintenance procedures is available.

### 4.3 Maintenance of Operating Facilities.

See Section 4.2 above.

### 4.4 Warning System.

No formal warning system is in effect.

### 4.5 Evaluation.

Since 1973, the facility has existed virtually without any maintenance, routine or otherwise. Both the outlet conduit and water supply system are reportedly functional; however, neither were operated in the presence of the inspection team. Formal operations and maintenance manuals need to be developed and a formal warning system put in effect.

## SECTION 5 HYDROLOGIC/HYDRAULIC EVALUATION

### 5.1 Design Data.

No formal design reports, calculations, or design data are available for any aspect of this facility.

### 5.2 Experience Data.

No formal records of daily rainfall and/or spillway discharge are available for this facility. The embankment failure in 1925 is well documented in PennDER files; however, no relative hydrologic or hydraulic data is available. The present emergency spillway was constructed as a result of that event.

### 5.3 Visual Observations.

On the date of inspection, no conditions were observed that would indicate the spillways could not perform satisfactorily during a flood event, within the limits of their design capacities. The lower portion of the emergency spillway discharge channel is deteriorated, characterized by severe concrete scaling, extensive cracking and some slab uplifting. Continued lack of maintenance increases the possibility that high flows could further damage the deteriorating spillway structure and possibly endanger the embankment.

### 5.4 Method of Analysis.

The facility has been analyzed in accordance with the procedures and guidelines established by the U. S. Army, Corps of Engineers, Baltimore District, for Phase I hydrologic and hydraulic evaluations. The analysis has been performed utilizing a modified version of the HEC-1 program developed by the U. S. Army, Corps of Engineers, Hydrologic Engineering Center, Davis, California. Analytical capabilities of the program are briefly described in the preface contained in Appendix D.

### 5.5 Summary of Analysis.

a. Spillway Design Flood (SDF). In accordance with procedures and guidelines contained in the National Guidelines For Safety Inspection of Dams for Phase I Investigations, the Spillway Design Flood (SDF) for Lebanon Reservoir Dam No. 1 ranges between the 1/2 PMF (Probable Maximum Flood) and the PMF. This classification is based on the relative size of the dam (small), and the potential hazard

of dam failure to downstream developments (high). Due to the high potential for loss of life and damage to downstream structures, the SDF for this facility is considered to be the PMF.

b. Results of Analysis.

Lebanon Reservoir Dam No. 1 was evaluated under near normal operating conditions. That is, the reservoir was initially at its normal pool or service spillway crest elevation of approximately 622.5 feet with the spillway discharging freely. The outlet conduit was assumed to be non-functional for the purpose of analysis. In any event, the flow capacity of the outlet conduit is not such that it would significantly increase the total discharge capabilities of the dam and reservoir. The primary discharge facilities consist of a service spillway and an adjacent emergency spillway. The service spillway consists of a broad-crested weir which discharges into a natural channel. The emergency spillway is comprised of a broad-crested weir which discharges into a rectangular chute channel.

Lebanon Reservoir Dam No. 2, located immediately upstream of Dam No. 1, was also evaluated in this analysis to determine its effects on Dam No. 1. It also was investigated under near normal operating conditions. That is, the reservoir was initially at its normal pool or spillway crest elevation of approximately 676.0 feet, with the spillway discharging freely and the outlet conduit closed. The spillway consists of a broad-crested weir which discharges into a natural channel. It was assumed that the outflow of Dam No. 2 discharged directly into the lower reservoir. All pertinent engineering calculations relative to the evaluation of Lebanon Reservoir Dam No. 1, including those pertaining to the upstream facility are included in Appendix D.

Overtopping analysis (using the Modified HEC-1 Computer Program) indicated that the discharge/storage capacity of Lebanon Reservoir Dam No. 1 can accommodate only about 16 percent of the PMF (the SDF) prior to the overtopping of its embankment, while Lebanon Reservoir Dam No. 2 can accommodate only about 21 percent of the PMF before overtopping occurs (Appendix D, Summary Input/Output Sheet, Sheet L). The low top of embankment at Dam No. 1 was inundated by depths of 1.8 feet for 6.3 hours under 1/2 PMF conditions and 2.5 feet for 8.5 hours under PMF conditions. The low top of embankment at Dam No. 2 was inundated by a depth of about 0.9 feet for 6.5 hours under PMF conditions. Since the SDF for each of the facilities is the PMF, each has a high potential for overtopping, and thus, for breaching under floods of less than SDF magnitude.

Since neither of the dams can safely pass a flood of at least 1/2 PMF magnitude, the possibility of failure of each under floods of 1/2 PMF magnitude or less was investigated (in accordance with Corps directive ETL-1110-2-234). Several possible alternatives were examined since it is difficult, if not impossible, to determine exactly how or if a specific dam will fail. The dams were evaluated in series in order to ascertain the overall effect of the present system on the downstream population in the event of a severe storm. The major concern of the breaching evaluations is with the impact of the various breach discharges on increasing downstream water surface elevations above those to be expected if breaching did not occur.

The Modified HEC-1 Computer Program was used for the breaching analysis with the assumption that the breaching of an earth dam would begin once its reservoir's water level reached the low top of dam elevation.

For each of the two dams, five possible modes of failure were investigated. Two sets of breach geometry were evaluated for each of two failure times (Appendix D, Sheet 23). The two sets of breach sections chosen were considered to be the minimum and maximum probable failure sections. The two failure times (total time for each breach section to reach its final dimensions), under which the minimum and maximum sections were investigated, were assumed to be a rapid time (0.5 hours) and a prolonged time (4.0 hours), so that a range of this most sensitive variable might be examined. In addition, an average possible set of breach conditions was analyzed, with a failure time of 2.0 hours.

The five failure plans described above were analyzed under 0.24 PMF conditions to ensure overtopping of both dams. In all cases, the breaching of the downstream Lebanon Reservoir Dam No. 1 began about 30 minutes ahead of the failure of the upstream Lebanon Reservoir Dam No. 2 (Appendix D, Sheet 25).

The peak breach outflows (resulting from 0.24 PMF conditions) at Lebanon Reservoir Dam No. 1 ranged from about 1810 cfs for the minimum section-maximum fail time scheme to about 8380 cfs for the maximum section-minimum fail time scheme (Appendix D, Sheet 25). The outflow from the average breach scheme was about 3520 cfs, compared to the non-breach 0.24 PMF outflow of approximately 740 cfs (Summary Input/Output Sheets, Sheets U and L).

At a section located about 2700 feet downstream from Lebanon Reservoir Dam No. 1 (Section 2, see Figure 1, Appendix E), the water surface elevation corresponding to the non-breach 0.24 PMF peak outflow was approximately 544.3 feet while the peak water surface elevation corresponding to the maximum section-minimum fail time breach scheme was about 546.4 feet (Appendix D, Sheet 26). The elevation of the residence at Section 2 is approximately 545 feet. Therefore, the increase in water surface elevation caused by the failures of Lebanon Reservoir Dams Nos. 1 and 2 was about 2.1 feet, with the breach water surface above the damage level of the house.

At Section 3 (see Figure 1), located approximately 4550 feet downstream of Dam No. 1, the maximum breach water surface elevation was about 533.8 feet, well below the damage level of the residences at about 538 feet (Summary Input/Output Sheets, Sheet V).

The water surface elevation corresponding to the non-breach 0.24 PMF peak outflow was approximately 520.4 feet at a section located about 6050 feet downstream from Lebanon Dam Reservoir No. 1 (Section 4, see Figure 1). The peak water surface elevation corresponding to the maximum section-minimum fail time breach scheme was about 522.6 (Appendix D, Sheet 26). The residence at Section 4 is approximately at elevation 520 feet. Thus, the increase in water surface elevation due to the breaches was about 2.2 feet, with the breach water surface above the damage level of the house.

At Section 5 (see Figure 1), located about 8650 feet downstream from Dam No. 1, the non-breach 0.24 PMF peak outflow resulted in a water surface elevation of approximately 503.9 feet. The maximum section-minimum fail time scheme resulted in a peak elevation of 507.5 feet, an increase of 3.6 feet (Appendix D, Sheet 26). The breach water surface level was above the damage level of the residence at Section 5, approximately at elevation 504.

The consequences of dam failure can be better envisioned if not only the increase in the height of the floodwave is considered, but also the great increase in the momentum of the larger and probably swifter moving volume of water. Therefore, the failures of Lebanon Reservoir Dams Nos. 1 and 2 are quite possible, and would probably lead to increased property damage and possibly to loss of life in the downstream regions.



#### 5.6 Spillway Adequacy.

As presented previously, under existing conditions, Lebanon Reservoir Dam No. 1 can accommodate only about 16 percent of the PMF prior to overtopping. Should a 0.24 PMF or larger event occur, the dam would be overtopped and could possibly fail, endangering downstream residences and increasing the potential for loss of life in the downstream regions. Therefore, the spillway is considered to be seriously inadequate.

SECTION 6  
EVALUATION OF STRUCTURAL INTEGRITY

6.1 Visual Observations.

a. Embankment. The embankment is considered to be in fair condition. Lack of adequate maintenance has resulted in overgrown slopes and a generally poor appearance; nevertheless, no evidence of excess embankment stresses, slope instability, or seepage through the downstream embankment face was observed. Heavy overgrowth across the embankment slopes and along the downstream toe hamper visual observation of critical conditions and should be removed.

b. Appurtenant Structures.

1. Service Spillway. The service spillway appears structurally sound and is presently in good condition.

2. Emergency Spillway. The condition of the emergency spillway is considered poor. The lower portion of the discharge channel is deteriorated, characterized by severe concrete scaling, extensive cracking and some slab uplifting. Without proper maintenance, it is possible that high flows could further damage the deteriorating spillway structure and possibly endanger the embankment.

3. Outlet Conduit. The outlet conduit is reportedly functional; however, it was not operated in the presence of the inspection team. Minor seepage ( $\approx 2$  gpm) was observed emanating around the conduit within the downstream valve chamber. This condition should be specifically addressed in future inspection and changes in flow rate and/or turbidity recorded. It is noted that control is not provided at the upstream end of the pipe. Should a leak or rupture develop within the conduit upstream of the gate valve along the downstream slope, there presently is no means of stopping the flow and thus, it is possible that serious erosion and/or instability could result.

6.2 Design and Construction Techniques.

No information is available that details the methods of design and/or construction.

6.3 Past Performance.

According to available correspondence and discussions

with representatives of the owner, the facility has performed satisfactorily since its last renovation in 1938.

#### 6.4 Seismic Stability.

The dam is located within Seismic Zone No. 1 and, thus may be subject to minor earthquake induced dynamic forces. As the facility appears well constructed and sufficiently stable, it is believed that it can withstand the expected dynamic forces; however, no calculations and/or investigations were performed to confirm this belief.

SECTION 7  
ASSESSMENT AND RECOMMENDATIONS FOR REMEDIAL MEASURES

7.1 Dam Assessment.

a. Safety. The visual inspection indicates the facility is inadequately maintained and in fair condition.

The size classification of the facility is small and its hazard classification is considered to be high. In accordance with the recommended guidelines, the Spillway Design Flood (SDF) for the facility ranges between the 1/2 PMF (Probable Maximum Flood) and the PMF. Due to the high potential for damage to downstream structures and possibly loss of life, the SDF is considered to be the PMF. Results of the hydrologic and hydraulic analysis indicate the facility will pass and/or store only about 16 percent of the PMF prior to embankment overtopping. A breach analysis indicates that failure under less than 1/2 PMF conditions could lead to increased downstream damage and potential for loss of life. Thus, based on screening criteria contained in the recommended guidelines, the spillway is considered to be seriously inadequate and the facility unsafe, non-emergency.

Deficiencies noted by the inspection team included heavy overgrowth across the embankment crest and slopes, rodent burrows along the downstream embankment face, a deteriorated emergency spillway, and minor seepage beneath the emergency spillway and around the outlet conduit. These deficiencies are, for the most part, attributable to a general lack of adequate maintenance since the facility was phased out of operation in 1973.

b. Adequacy of Information. The available data are considered sufficient to make a reasonable Phase I assessment of the facility.

c. Urgency. The recommendations listed below should be implemented immediately.

d. Necessity for Additional Investigations. Additional investigations are considered necessary and are listed in Section 7.2 below.

7.2 Recommendations/Remedial Measures.

It is recommended that the owner immediately:

a. Develop a formal emergency warning system to notify downstream residents should hazardous conditions develop. Included in the plan should be provisions for around-the-clock surveillance of the facility during periods of unusually heavy precipitation.

b. Have the facility evaluated by a registered professional engineer experienced in hydrology and hydraulic structures and take remedial measures deemed necessary to make the facility hydraulically adequate and the emergency spillway structurally sound.

c. Clear all excess vegetation from the embankment crest and slopes. In addition, all burrowing animals inhabiting the embankment should be exterminated and their burrows filled.

d. Develop formal manuals of operation and maintenance to ensure future proper care of the facility.

e. Specifically address in all future inspections the seepage conditions beneath the emergency spillway and around the outlet conduit at the downstream embankment toe noting changes in turbidity and/or rate of flow.

f. Provide upstream (inlet end) control of flow through the outlet conduit or develop a plan to control flow through the conduit at the inlet in the event emergency conditions develop in the pipe within the embankment.

APPENDIX A

VISUAL INSPECTION CHECKLIST AND FIELD SKETCHES

# CHECK LIST VISUAL INSPECTION PHASE 1

NAME OF DAM Lebanon Reservoir Dam No. 1 STATE Pennsylvania COUNTY Lebanon

NDI # PA 00595 PENNDER # 38-1

TYPE OF DAM Earth SIZE Small HAZARD CATEGORY High

DATE(S) INSPECTION 8 November 1979 WEATHER Ptly cloudy TEMPERATURE 40° @ Noon

POOL ELEVATION AT TIME OF INSPECTION 622.7 M.S.L.

TAILWATER AT TIME OF INSPECTION N/A M.S.L.

## INSPECTION PERSONNEL

B. M. Mihalcin

D. L. Bonk

D. J. Spaeder

## OWNER REPRESENTATIVES

None Present

## OTHERS

RECORDED BY B. M. Mihalcin

# EMBANKMENT

| ITEM   | OBSERVATIONS/REMARKS/RECOMMENDATIONS                     | NDI# PA - 00595 |
|--|--|-----------------|
| SURFACE CRACKS   | None observed.   |                 |
| UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE      | None observed.   |                 |
| SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES | None observed.   |                 |
| VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST         | Horizontal - good.<br>Vertical - good.                   |                 |
| RIPRAP FAILURES  | Riprap patchy, but, no significant erosion was observed. |                 |
| JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM  | Good.  |                 |



# EMBANKMENT

| ITEM   | OBSERVATIONS/REMARKS/RECOMMENDATIONS   | NDI# PA - 00595 |
|--|--|-----------------|
| DAMP AREAS<br>IRREGULAR VEGETA-<br>TION (LUSH OR DEAD<br>PLANTS) | No damp areas were observed on the downstream embankment face. Heavy overgrowth, including trees and thick brush, covers the entire embankment.  |                 |
| ANY NOTICEABLE<br>SEEPAGE  | No evidence of seepage through the downstream embankment face was observed. Minor seepage ( $\leq 1$ gpm) observed emanating from beneath the discharge end of the emergency spillway. Seepage or leakage ( $\approx 2$ gpm) observed around the blowoff conduit within the valve chamber located at the downstream embankment toe.  |                 |
| STAFF GAGE AND<br>RECORDER                                       | None.  |                 |
| DRAINS   | Three 6-inch diameter clay drains project through the downstream rock toe and discharge into a small rock-lined ditch parallel to the toe. Very small discharge on day of inspection. Two more 6-inch clay drains discharge into the channel several feet downstream of the blowoff conduit and apparently drain the left side of the embankment. Another drain was observed beneath the center of the downstream end of the emergency spillway. |                 |
|  |  |                 |

# OUTLET WORKS

| ITEM   | OBSERVATIONS/REMARKS/RECOMMENDATIONS   | NDI# PA - 00595 |
|--|--|-----------------|
| INTAKE STRUCTURE   | Blowoff intake was submerged and could not be observed.  |                 |
| OUTLET CONDUIT<br>(CRACKING AND<br>SPALLING OF CON-<br>CRETE SURFACES) | 16-inch diameter cast iron blowoff pipe.   |                 |
| OUTLET STRUCTURE   | Valve chamber at downstream end of blowoff line. Concrete in good condition, but, hatch doors on top unattached and susceptible to vandalism.  |                 |
| OUTLET CHANNEL   | Natural channel-unobstructed.  |                 |
| GATE(S) AND OPERA-<br>TIONAL EQUIPMENT                                 | Two apparent valves on blowoff line. One in valve chamber at toe of dam is not operable. A second valve stem was observed in a curb box structure about mid-height on the downstream slope of the dam. This valve reportedly controls blowoff discharge. |                 |
|  |  |                 |

# **EMERGENCY SPILLWAY**

| ITEM                             | OBSERVATIONS/REMARKS/RECOMMENDATIONS   | NDI# PA - 00595 |
|----------------------------------|--|-----------------|
| TYPE AND CONDITION               | Concrete chute channel in poor condition.  |                 |
| APPROACH CHANNEL                 | N/A.   |                 |
| SPILLWAY CHANNEL AND SIDEWALLS   | Channel floor-severely scaled and cracked. Some slab uplifting apparent and seepage through joints was observed. Many joints contain swamp willow shrubs.  |                 |
| STILLING BASIN PLUNGE POOL       | See below.   |                 |
| DISCHARGE CHANNEL                | The emergency spillway discharges into a broad, flat, agricultural area located immediately downstream of the dam. The natural stream channel is physically defined by a line of trees and brush that divides adjoining fields and pastures. |                 |
| BRIDGE AND PIERS EMERGENCY GATES | The remnants of a steel supported footbridge span both the service and emergency spillways. Only the steel supports remain while all planking has been removed.  |                 |

# **SERVICE SPILLWAY**


| ITEM               | OBSERVATIONS/REMARKS/RECOMMENDATIONS  | NDI# PA - 00595 |
|--------------------|---|-----------------|
| TYPE AND CONDITION | Concrete chute channel with masonry wingwalls in good condition.  |                 |
| APPROACH CHANNEL   | N/A.  |                 |
| OUTLET STRUCTURE   | N/A.  |                 |
| DISCHARGE CHANNEL  | Trapezoidal-shaped rock-lined channel. Small flows are directed into a shallow farm pond located several hundred feet downstream and to the east of the facility. Larger flows apparently overtop the left channel bank, approximately 150 feet downstream of the spillway crest and discharge into a diversion channel that routes flow to the original stream channel downstream of the outlet conduit. |                 |
|                    |   |                 |

# INSTRUMENTATION

| ITEM                  | OBSERVATIONS/REMARKS/RECOMMENDATIONS | NDI# PA - 00595 |
|-----------------------|--------------------------------------|-----------------|
| MONUMENTATION SURVEYS | None.                                |                 |
| OBSERVATION WELLS     | None.                                |                 |
| WEIRS                 | None.                                |                 |
| PIEZOMETERS           | None.                                |                 |
| OTHERS                |                                      |                 |
|                       |                                      |                 |

# RESERVOIR AREA AND DOWNSTREAM CHANNEL


| ITEM  | OBSERVATIONS/REMARKS/RECOMMENDATIONS   | ND# PA - 00595 |
|---|--|----------------|
| SLOPES:<br>RESERVOIR                            | The dam is located at the foot of heavily forested, steep slopes. The reservoir is flanked to the northeast and west by gently to moderately sloped farmland.  |                |
| SEDIMENTATION                                   | None observed.   |                |
| DOWNSTREAM CHANNEL (OBSTRUCTIONS, DEBRIS, ETC.) | Low flows through the service spillway are routed through a small man-made channel that directs discharge downstream and to the right of the facility. Larger flows from the emergency spillway are routed into the original stream immediately downstream of the embankment below the outlet conduit. |                |
| SLOPES:<br>CHANNEL VALLEY                       | Gently sloped farmlands.   |                |
| APPROXIMATE NUMBER OF HOMES AND POPULATION      | There are approximately 1/2 dozen homes and farms located along the stream within several miles of the dam. It is estimated that 20 to 30 persons could be affected by a breach of the embankment.   |                |



LEBANON RESERVOIR DAM NO. 1  
GENERAL PLAN - FIELD INSPECTION NOTES

# IFBANON DAM NO. 1

PROFILE OF DAMCREST  
FROM FIELD SURVEY





APPENDIX B  
ENGINEERING DATA CHECKLIST

**CHECK LIST  
ENGINEERING DATA  
PHASE I**

NAME OF DAM Lebanon Reservoir Dam No. 1

| ITEM   | REMARKS   | NDI# PA - 00595 |
|--|---|-----------------|
| PERSONS INTERVIEWED<br>AND TITLE                 | Edward M. Keener (City of Lebanon, Engineer).<br>Chris Siegrist (Water Authority Superintendent).   |                 |
| REGIONAL VICINITY<br>MAP                         | See Figure 1, Appendix E.   |                 |
| CONSTRUCTION<br>HISTORY                          | Originally constructed in 1871. Designed by H.P.M. Birkinbine of Philadelphia, Pennsylvania. Overtopped and breached in 1925. Reconstructed in 1926. Additional modifications made in 1938. |                 |
| AVAILABLE DRAWINGS                               | Several miscellaneous design drawings (no complete sets) are available from both the owner and PennDER.   |                 |
| TYPICAL DAM<br>SECTIONS                          | See Figure 3, Appendix E.   |                 |
| OUTLETS:<br>PLAN<br>DETAILS<br>DISCHARGE RATINGS | See Figures 2, 3, and 4, Appendix E.<br>Discharge curves are not available.   |                 |

**CHECK LIST  
ENGINEERING DATA  
PHASE I  
(CONTINUED)**

| ITEM  | REMARKS                          | NDI# PA - 00595 |
|---|----------------------------------|-----------------|
| SPILLWAY:<br>PLAN<br>SECTION<br>DETAILS   | See Figures 3 and 4, Appendix E. |                 |
| OPERATING EQUIP-<br>MENT PLANS AND<br>DETAILS   | See Figures 2 and 3, Appendix E. |                 |
| DESIGN REPORTS  | None available.                  |                 |
| GEOLOGY REPORTS   | None available.                  |                 |
| DESIGN COMPUTATIONS:<br>HYDROLOGY AND<br>HYDRAULICS<br>STABILITY ANALYSES<br>SEEPAGE ANALYSES | None available.                  |                 |
| MATERIAL<br>INVESTIGATIONS:<br>BORING RECORDS<br>LABORATORY TESTING<br>FIELD TESTING          | None available.                  |                 |

**CHECK LIST  
ENGINEERING DATA  
PHASE I  
(CONTINUED)**

| ITEM   | REMARKS  | NDI# PA - 00595 |
|--|--|-----------------|
| BORROW SOURCES   | Not known.   |                 |
| POST CONSTRUCTION<br>DAM SURVEYS                           | None recorded.   |                 |
| POST CONSTRUCTION<br>ENGINEERING<br>STUDIES AND<br>REPORTS | The upper dam (referred to as Rexmont No. 2 Dam or Lebanon Reservoir Dam No. 2, NDI No. PA-00594, PennDER No. 38-2) was inspected in November, 1978 by Berger Associates, Inc., of Harrisburg, Pennsylvania. Results are contained in PennDER files in a report dated May, 1979. |                 |
| HIGH POOL RECORDS  | Not known.   |                 |
| MONITORING SYSTEMS   | None.  |                 |
| MODIFICATIONS  | Dam was partially reconstructed in 1926 after overtopping and failing in 1925. Additional modifications were made in 1938 (see Section 2.1.b.1 and Figures 3 and 4, Appendix E).   |                 |

**CHECK LIST  
ENGINEERING DATA  
PHASE I  
(CONTINUED)**

| ITEM  | REMARKS  | NDI# PA - 00595 |
|---|--|-----------------|
| PRIOR ACCIDENTS OR<br>FAILURES                          | Dam was overtopped and breached on July 25, 1925. No fatalities were recorded.   |                 |
| MAINTENANCE:<br>RECORDS<br>MANUAL                       | None available.  |                 |
| OPERATION:<br>RECORDS<br>MANUAL                         | None available.  |                 |
| OPERATIONAL<br>PROCEDURES                               | Essentially self-regulating. No specific operating procedures exist.   |                 |
| WARNING SYSTEM<br>AND/OR<br>COMMUNICATION<br>FACILITIES | None.  |                 |
| MISCELLANEOUS   | Dam used to supply water to City of Lebanon prior to 1973. Facility currently used strictly for recreational purposes. Blowoff and supply lines are all reportedly functional. |                 |

GAI CONSULTANTS, INC.

**CHECK LIST  
HYDROLOGIC AND HYDRAULIC  
ENGINEERING DATA**

NDI ID # PA-00595  
PENNDER ID # 38-1

SIZE OF DRAINAGE AREA: 0.6 square miles (local); 1.2 square miles (total).  
ELEVATION TOP NORMAL POOL: 622.5 STORAGE CAPACITY: 55 acre-feet  
ELEVATION TOP FLOOD CONTROL POOL: - STORAGE CAPACITY: -  
ELEVATION MAXIMUM DESIGN POOL: - STORAGE CAPACITY: -  
ELEVATION TOP DAM: 625.3 STORAGE CAPACITY: 82 acre-feet.

**SPILLWAY DATA**

CREST ELEVATION: 662.5 feet (service); 623.0 feet (emergency).  
TYPE: Uncontrolled rectangular chute channels.  
CREST LENGTH: 10.5 feet (service; 37.8 feet (emergency).  
CHANNEL LENGTH: 50 feet (service); 180 feet (emergency).  
SPILLOVER LOCATION: Near right abutment.  
NUMBER AND TYPE OF GATES: None.

**OUTLET WORKS**


TYPE: 16-inch diameter case iron blowoff conduit.  
LOCATION: Near the center of the embankment.  
ENTRANCE INVERTS: 602 feet (estimated zero storage elevation).  
EXIT INVERTS: 594.9 feet.  
EMERGENCY DRAWDOWN: FACILITIES: 16-inch diameter gate valve.

**HYDROMETEOROLOGICAL GAGES**

TYPE: None.  
LOCATION: -  
RECORDS: -

MAXIMUM NON-DAMAGING DISCHARGE: Not known.

APPENDIX C  
PHOTOGRAPHS



LEBANON RESERVOIR DAM NO. 1  
PHOTOGRAPH KEY MAP



PHOTOGRAPH 1 View, looking upstream, of the spillways at Lebanon Reservoir Dam No. 1.

PHOTOGRAPH 2 View of the emergency spillway channel as seen from the service spillway.

PHOTOGRAPH 3 View of the spillways as seen from atop the right wingwall of the service spillway.

PHOTOGRAPH 4 View, looking upstream, of the discharge end of the emergency spillway channel. Note the heavy overgrowth.



3



4



1



2

PHOTOGRAPH 5 View of the boarded-up masonry gate house located along the upstream embankment slope.

PHOTOGRAPH 6 View of the discharge end of the outlet conduit.

PHOTOGRAPH 7 View of the interior of the valve chamber located at the downstream embankment toe. Leakage observed around the outlet conduit within the chamber was estimated at about 2 gpm. The valve within the chamber is reportedly inoperable.


PHOTOGRAPH 8 View of the curb box accessing the stem of an outlet conduit valve near the middle of the downstream slope to the right (looking downstream) of the valve chamber.




6



8



5



7

PHOTOGRAPH 9 View of the upstream embankment face as seen from the gate house footbridge.

PHOTOGRAPH 10 View of a 6-inch diameter clay pipe drain discharging into a small rock-lined ditch that parallels the downstream embankment toe between the emergency spillway and outlet conduit.

PHOTOGRAPH 11 1959 view of the embankment as seen from the right abutment (note: compare with Overview Photograph of downstream face).

PHOTOGRAPH 12 1959 view of Lebanon Reservoir Dam No. 1 as seen from atop the crest of Lebanon Reservoir Dam No. 2.



10



12



9



11

APPENDIX D  
HYDROLOGY AND HYDRAULICS ANALYSES

## PREFACE

The modified HEC-1 program is capable of performing two basic types of hydrologic analyses: 1) the evaluation of the overtopping potential of the dam; and 2) the estimation of the downstream hydrologic-hydraulic consequences resulting from assumed structural failures of the dam. Briefly, the computational procedures typically used in the dam overtopping analysis are as follows:

a. Development of an inflow hydrograph(s) to the reservoir.

b. Routing of the inflow hydrograph(s) through the reservoir to determine if the event(s) analyzed would overtop the dam.

c. Routing of the outflow hydrograph(s) from the reservoir to desired downstream locations. The results provide the peak discharge(s), time(s) of the peak discharge(s), and the maximum stage(s) of each routed hydrograph at the downstream end of each reach.

The evaluation of the hydrologic-hydraulic consequences resulting from an assumed structural failure (breach) of the dam is typically performed as shown below.

a. Development of an inflow hydrograph(s) to the reservoir.

b. Routing of the inflow hydrograph(s) through the reservoir.

c. Development of a failure hydrograph(s) based on specified breach criteria and normal reservoir outflow.

d. Routing of the failure hydrograph(s) to desired downstream locations. The results provide estimates of the peak discharge(s), time(s) to peak and maximum water surface elevations of failure hydrographs for each location.



# HYDROLOGY AND HYDRAULIC ANALYSIS DATA BASE

NAME OF DAM: LEBANON RESERVOIR DAM NO. 1

PROBABLE MAXIMUM PRECIPITATION (PMP) = 23.2 INCHES/24 HOURS <sup>(1)</sup>

| STATION   | 1         | 2         | 3    |
|---|-----------|-----------|------|
| STATION DESCRIPTION   | Dam No. 2 | Dam No. 1 |      |
| DRAINAGE AREA (SQUARE MILES)  | 0.6       | 0.6       |      |
| CUMULATIVE DRAINAGE AREA<br>(SQUARE MILES)                                    | -         | 1.2       |      |
| ADJUSTMENT OF PMF FOR<br>DRAINAGE AREA LOCATION (%) <sup>(1)</sup>            | Zone 6    | Zone 6    |      |
| 6 HOURS   | 113       | 113       |      |
| 12 HOURS  | 123       | 123       |      |
| 24 HOURS  | 132       | 132       |      |
| 48 HOURS  | 143       | 143       |      |
| 72 HOURS  | -         | -         |      |
| SNYDER HYDROGRAPH PARAMETERS  |           |           |      |
| ZONE (2)  | 15c       | 15c       |      |
| C <sub>p</sub> (3)  | 0.82      | 0.82      |      |
| C <sub>t</sub> (3)  | 2.78      | 2.78      |      |
| L (MILES) (4)   | 1.10      | 1.9       |      |
| L <sub>ca</sub> (MILES) (4)   | 0.51      | 1.1       |      |
| t <sub>p</sub> = C <sub>t</sub> (L · L <sub>ca</sub> ) <sup>0.3</sup> (HOURS) | 2.34      | 3.47      |      |
| SPILLWAY DATA   |           | (5)       | (6)  |
| CREST LENGTH (FEET)   | 14.5      | 10.5      | 37.8 |
| FREEBOARD (FEET)  | 3.8       | 2.8       | 2.3  |

(1) HYDROMETEOROLOGICAL REPORT 33, U.S. ARMY CORPS OF ENGINEERS, 1956

(2) HYDROLOGIC ZONE DEFINED BY CORPS OF ENGINEERS, BALTIMORE DISTRICT, FOR DETERMINATION OF SNYDER COEFFICIENTS (C<sub>p</sub> AND C<sub>t</sub>).

(3) SNYDER COEFFICIENTS

(4) L = LENGTH OF LONGEST WATERCOURSE FROM DAM TO BASIN DIVIDE.

L<sub>ca</sub> = LENGTH OF LONGEST WATERCOURSE FROM DAM TO POINT OPPOSITE BASIN CENTROID.

(5) SERVICE SPILLWAY

(6) EMERGENCY SPILLWAY

ECT DAM SAFETY INSPECTION  
LEBANON DAM No. 1  
BY DTT DATE 1-11-80 PROJ. NO. 79-203-595  
CHKD. BY DLB DATE 1-31-80 SHEET NO. 1 OF 26



### DAM STATISTICS

- HEIGHT OF DAM = 30 FEET (FIELD MEASUREMENT)
- NORMAL POOL STORAGE CAPACITY =  $18 \times 10^6$  GALLONS  
= 55.2 ACRE-FT (SEE NOTE 1)
- MAXIMUM POOL STORAGE CAPACITY = 82 ACRE-FT (HEC-1 OUTPUT)
- DRAINAGE AREA =  $0.63 = \underline{0.6}$  SQ. MI. { PLANIMETERED ON USGS  
7.5 MINUTE TOP 250'S:  
RICHLAND AND LEBANON, PA. }
- ELEVATION OF TOP OF DAM (DESIGN) = 626.0 (FIGURE 3)
- ELEVATION OF TOP OF DAM (FIELD) = 625.3
- NORMAL POOL ELEVATION = 622.5 (FIGURE 3 AND FIELD NOTES)
- UPSTREAM INLET INVERT ELEVATION = 603 (FIGURE 2)
- DOWNSTREAM OUTLET INVERT (FIELD) = 599.9
- STREAMBED AT DAM CENTERLINE = 598.0 (ESTIMATE)

NOTE 1: OBTAINED FROM "REPORT UPON DAM No. 1 OF THE LEBANON CITY  
WATER WORKS," DECEMBER, 1914, FOUND IN PERMITS FILES.

SUBJECT DAM SAFETY INSPECTION  
LEBANON DAM No. 1  
 BY DJS DATE 1-11-80 PROJ. NO. 79-303-595  
 CHKD. BY DLG DATE 1-31-80 SHEET NO. 2 OF 26



Engineers • Geologists • Planners  
 Environmental Specialists

### DAM CLASSIFICATION

DAM SIZE: SMALL

(REF 1, TABLE 1)

HAZARD CLASSIFICATION: HIGH

(FIELD OBSERVATION)

REQUIRED SDF:  $\frac{1}{2}$  PMF TO PMF

(REF 1, TABLE 3)

### HYDROGRAPH PARAMETERS

LENGTH OF LONGEST WATERCOURSE:  $L = 1.9$  MILES

LENGTH OF LONGEST WATERCOURSE FROM DAM

TO A POINT OPPOSITE BASIN CENTROID:  $L_{CA} = 1.1$  MILES

{ MEASURED ON 1:25,000 TOPO  
 QUADS: LEBANON AND  
 RICHLAND, VA. }

$$C_e = 2.78$$

$$C_p = 0.89$$

{ SUPPLIED BY COE, ZONE 15C, }  
 SUSQUEHANNA RIVER BASIN.

$$\begin{aligned} \text{SNYDER'S STANDARD LAG: } T_p &= C_e (L \cdot L_{CA})^{0.3} \\ &= 2.78 (1.9 \times 1.1)^{0.3} \\ &= \underline{3.47 \text{ HOURS}} \end{aligned}$$

(NOTE: HYDROGRAPH VARIABLES USED HERE ARE DEFINED IN REFERENCE 3,  
 IN SECTION ENTITLED "SNYDER SYNTHETIC UNIT HYDROGRAPH.")

SUBJECT DAM SAFETY INSPECTION  
LEBANON DAM No. 1  
 BY DJS DATE 1-11-80 PROJ. NO. 79-303-595  
 CHKD. BY DLB DATE 1-31-80 SHEET NO. 3 OF 26



### RESERVOIR CAPACITY

#### RESERVOIR SURFACE AREAS:

SURFACE AREA (SA.) AT NORMAL POOL (ELEV 622.5) = 8.5 ACRES  
 S.A. @ ELEV 640 = 23.7 ACRES

(PLANIMETERED ON U.S.G.S. TOPO QUAD, RICHLAND, PA)

ELEVATION OF LOW TOP OF DAM = 625.3 (FIELD NOTES)  
 BY LINEAR INTERPOLATION BETWEEN ELEVATIONS 640 AND 622.5,

SA @ ELEV 625.3 = 10.9 ACRES

#### RESERVOIR ELEVATION @ "0" STORAGE

STORAGE @ NORMAL POOL = 1/3 HA (ASSUMED CONIC RELATIONSHIP)

STORAGE = 55.2 ACRE-FT  
 SURFACE AREA (A) = 8.5 ACRES } @ NORMAL POOL

$$\therefore H = \frac{(3)(55.2)}{(8.5)} = 19.5 \text{ FT}$$

ZERO STORAGE ELEVATION = 622.5 - 19.5 = 603.0

NOTE: IN ORDER TO COMPUTE AN ELEVATION-STORAGE RELATIONSHIP, WITH A STORAGE VOLUME OF 55.2 AC-FT AT ELEVATION 622.5, THE ABOVE COMPUTED ZERO STORAGE ELEVATION MUST BE USED IN THE MEC-1 PROGRAM. THE CALCULATED ELEVATION SEEMS TO BE A REASONABLE ESTIMATE OF THE ACTUAL MINIMUM RESERVOIR ELEVATION, BASED ON AVAILABLE DESIGN DRAWINGS.

S CT DAM SAFETY INSPECTION  
LEDANON DAM No. 1  
BY DJS DATE 1-11-80 PROJ. NO. 79-393-595  
CHKD. BY DLB DATE 1-31-80 SHEET NO. 4 OF 26



RESERVOIR ELEVATION - STORAGE RELATIONSHIP:

THE ELEVATION-STORAGE RELATIONSHIP IS COMPUTED INTERNALLY BY THE HEC-1 PROGRAM, BASED ON THE ELEVATION/SURFACE AREA DATA GIVEN ON SHEET 3. THE CONIC METHOD IS USED TO ESTIMATE STORAGE VOLUMES.

PMP CALCULATIONS

APPROXIMATE RAINFALL INDEX IS 27.2 INCHES, CORRESPONDING TO A DURATION OF 24 HOURS AND AN AREA OF 920 SQUARE MILES, LOCATED IN SOUTH EASTERN PENNSYLVANIA.

(REF 3, FIG. 1)

- DEPTH-AREA-DURATION ZONE #6 (REF 3, FIG. 1)

- DRAINAGE AREA  $\leq$  0.6 SQUARE MILES; ASSUME DATA CORRESPONDING TO A 10-SQUARE MILE AREA IS REPRESENTATIVE OF THIS BASIN:

| <u>DURATION (HRS)</u> | <u>PERCENT OF INDEX RAINFALL</u> |                 |
|-----------------------|----------------------------------|-----------------|
| 6                     | 113                              |                 |
| 12                    | 123                              | (REF 3, FIG. 2) |
| 24                    | 132                              |                 |
| 48                    | 143                              |                 |

- HOP DROOK FACTOR (ADJUSTMENT FOR BASIN SHAPE AND FOR THE LESSER LIKELIHOOD OF A SEVERE STORM CENTERING OVER A SMALL BASIN) FOR A DRAINAGE AREA OF 0.6 SQUARE MILES IS 0.80.

(REF 4, P. 48)


PROJECT DAM SAFETY INSPECTION  
LEBANON DAM No. 1  
 BY DJS DATE 1-11-89 PROJ. NO. 79-303-595  
 CHKD. BY DLB DATE 1-31-80 SHEET NO. 5 OF 26

**gai**  
 CONSULTANTS, INC.

Engineers • Geologists • Planners  
 Environmental Specialists


SPILLWAY CAPACITY

SPILLWAY CROSS-SECTION:




SPILLWAY PROFILES:

SERVICE SPILLWAY:



EMERGENCY SPILLWAY:



- BASED ON FIELD NOTES  
 AND DESIGN DRAWINGS,  
 FIGURE 3

ECT                      DAM SAFETY INSPECTION  
                     LEBANON DAM No. 1  
BY DJS DATE 1-14-80 PROJ. NO. 79-303-595  
CHKD. BY DLS DATE 1-31-80 SHEET NO. 6 OF 26



THE PRIMARY DISCHARGE FACILITIES CONSIST OF A SERVICE SPILLWAY AND AN ADJACENT EMERGENCY SPILLWAY. THE SERVICE SPILLWAY CONSISTS OF A BROAD-CRESTED WEIR WHICH DISCHARGES INTO A NATURAL CHANNEL. THE EMERGENCY SPILLWAY IS ESSENTIALLY COMPRISED OF A BROAD-CRESTED WEIR WHICH DISCHARGES INTO A RECTANGULAR CHUTE CHANNEL.

DISCHARGE OVER EACH WEIR CAN BE ESTIMATED BY THE RELATION

$$Q = CLH^{3/2} \quad (\text{REF 5, p. 5-23})$$

WHERE  
 $Q$  = DISCHARGE OVER THE WEIR, IN CFS,  
 $C$  = DISCHARGE COEFFICIENT,  
 $L$  = LENGTH OF WEIR CREST, IN FEET,  
 $H$  = TOTAL HEAD ON CREST, IN FEET.

SERVICE SPILLWAY CAPACITY:

THE CREST OF THE SERVICE SPILLWAY IS AT ELEVATION 628.5. THE LENGTH OF THE CREST IS APPROXIMATELY 10.5 FEET. THE DISCHARGE COEFFICIENT WILL BE ASSUMED TO BE ON THE ORDER OF 2.6. THIS SLIGHTLY CONSERVATIVE VALUE SHOULD ACCOUNT FOR ANY MINOR APPROACH LOSSES OR ENTRANCE LOSSES WHICH MAY EXIST, AS WELL AS ANY EFFECTS DUE TO THE BRIDGE SUPPORT STEEL. (REF 5, TABLE 5-3)

PROJECT DAM SAFETY INSPECTION  
LEBANON DAM No. 1  
 BY DJS DATE 1-14-80 PROJ. NO. 79-203-595  
 CHKD. BY DLA DATE 1-31-80 SHEET NO. 7 OF 26



SERVICE SPILLWAY RATING TABLE:

| RESERVOIR<br>ELEVATION<br>(FT) | H<br>(FT) | Q*<br>(CFS) | RESERVOIR<br>ELEVATION<br>(FT) | H<br>(FT) | Q*<br>(CFS) |
|--------------------------------|-----------|-------------|--------------------------------|-----------|-------------|
| 622.5                          | 0         | 0           | 628.0                          | 5.5       | 350         |
| 623.0                          | 0.5       | 10          | 629.0                          | 6.5       | 450         |
| 624.0                          | 1.5       | 50          | 630.0                          | 7.5       | 560         |
| 625.0                          | 2.5       | 110         | 631.0                          | 8.5       | 680         |
| (LOW TOP<br>OF DAM) 625.3      | 2.8       | 130         | 632.0                          | 9.5       | 800         |
| 626.0                          | 3.5       | 190         | 633.0                          | 10.5      | 930         |
| 627.0                          | 4.5       | 260         | 635.0                          | 12.5      | 1210        |

$$* Q = CLH^{3/2} = (2.6)(10.5)(H^{3/2}) \\ = 27.3 H^{3/2}$$

EMERGENCY SPILLWAY CAPACITY:

THE CREST OF THE EMERGENCY SPILLWAY IS APPROXIMATELY AT ELEVATION 623.0. THE EFFECTIVE LENGTH OF THE CREST IS 19.0 + 18.8, OR 37.8 FEET. A DISCHARGE COEFFICIENT OF ABOUT 2.6 IS ASSUMED. THIS SLIGHTLY CONSERVATIVE VALUE SHOULD ACCOUNT FOR ANY MINOR PIER LOSSES, APPROACH LOSSES, BRIDGE CHORD LOSSES, ETC., WHICH MAY EXIST.

(REF 5, TABLE 5-3)



SUBJECT DAM SAFETY INSPECTION  
LEBANON DAM No. 2  
 BY DTS DATE 1-14-80 PROJ. NO. 79-203-595  
 CHKD. BY DLB DATE 1-31-80 SHEET NO. 8 OF 26



Engineers • Geologists • Planners  
 Environmental Specialists

EMERGENCY SPILLWAY RATING TABLE :

| RESERVOIR<br>ELEVATION    | H    | Q *   | RESERVOIR<br>ELEVATION | H    | Q *   |
|---------------------------|------|-------|------------------------|------|-------|
| (FT)                      | (FT) | (CFS) | (FT)                   | (FT) | (CFS) |
| 623.0                     | 0    | 0     | 629.0                  | 6.0  | 1440  |
| 624.0                     | 1.0  | 100   | 630.0                  | 7.0  | 1820  |
| 625.0                     | 2.0  | 290   | 631.0                  | 8.0  | 2220  |
| (LOW TOP<br>OF DAM) 625.3 | 2.3  | 340   | 632.0                  | 9.0  | 2650  |
| 626.0                     | 3.0  | 510   | 633.0                  | 10.0 | 3110  |
| 627.0                     | 4.0  | 790   | 635.0                  | 12.0 | 4090  |
| 628.0                     | 5.0  | 1100  |                        |      |       |

$$Q = CLH^{3/2} = (2.6)(37.9)H^{3/2} \\ = 99.3 H^{3/2}$$

EMBANKMENT RATING CURVE

ASSUME THAT THE EMBANKMENT BEHAVES ESSENTIALLY AS A CRESTED WEIR WHEN OVERTOPPED. THUS, THE DISCHARGE CAN BE ESTIMATED BY THE RELATIONSHIP

$$Q = CLH^{3/2} \quad (\text{REF 5, p. 5-23})$$

WHERE  
 Q = DISCHARGE OVER EMBANKMENT, IN CFS,  
 L = LENGTH OF EMBANKMENT OVERTOPPED, IN FEET,  
 H = HEAD ON WEIR; IN THIS CASE, IT IS THE AVERAGE, "FLOW-AREA" WEIGHTED HEAD ABOVE THE CREST, USING THE LOW TOP OF DAM AS THE DATUM,  
 C = COEFFICIENT OF DISCHARGE; DEPENDENT ON THE HEAD AND THE WEIR BREADTH.

PROJECT DAM SAFETY INSPECTION  
LEBANON DAM No. 1  
 BY WJS DATE 1-14-80 PROJ. NO. 79-203-595  
 CHKD. BY DLB DATE 1-31-80 SHEET NO. 9 OF 26



ASSUME THAT INCREMENTAL DISCHARGES FOR SUCCESSIVE RESERVOIR ELEVATIONS ARE APPROXIMATELY TRAPEZOIDAL IN CROSS-SECTIONAL FLOW AREA. THEN ANY INCREMENTAL AREA OF FLOW (BETWEEN SPECIFIED RESERVOIR ELEVATIONS) IS APPROXIMATELY EQUAL TO  $H_i [(L_1 + L_2)/2]$ , WHERE  $L_1$  = LENGTH OF OVERTOPPED EMBANKMENT AT HIGHER ELEVATION,  $L_2$  = LENGTH AT LOWER ELEVATION,  $H_i$  = DIFFERENCE IN ELEVATIONS. THUS, THE TOTAL AVERAGE "FLOW-AREA" WEIGHTED HEAD,  $H_w$ , IS APPROXIMATELY EQUAL TO (TOTAL FLOW AREA /  $L_2$ ).

EMBANKMENT RATING TABLE:

| RESERVOIR<br>ELEVATION<br>(FT) | ①<br>LENGTH<br>OVERTOPPED,<br>$L_1$<br>(FT) | $L_2$<br>(FT) | INCREMENTAL<br>HEAD, $H_i$<br>(FT) | ②<br>INCREMENTAL<br>FLOW AREA, $A_i$<br>(FT <sup>2</sup> ) | TOTAL FLOW<br>AREA, $A_T$<br>(FT <sup>2</sup> ) | ③<br>WEIGHTED<br>HEAD, $H_w$<br>(FT) | ④<br>$\frac{H_w}{L}$ | ⑤<br>C | ⑥<br>Q<br>(CFS) |
|--------------------------------|---|---------------|------------------------------------|--|---|--------------------------------------|----------------------|--------|-----------------|
| 625.3                          | 0   | 0             | 0                                  | 0  | 0   | 0                                    | 0                    | —      | 0               |
| 625.4                          | 25  | 0             | 0.1                                | 1  | 1   | 0                                    | 0                    | —      | 0               |
| 626.0                          | 100   | 25            | 0.6                                | 38   | 39  | 0.4                                  | 0.03                 | 3.01   | 80              |
| 626.7                          | 125   | 100           | 0.7                                | 79   | 118   | 0.9                                  | 0.08                 | 3.03   | 320             |
| 626.9                          | 210   | 125           | 0.2                                | 34   | 152   | 0.7                                  | 0.06                 | 3.03   | 370             |
| 627.0                          | 320   | 210           | 0.1                                | 27   | 179   | 0.6                                  | 0.05                 | 3.03   | 450             |
| 627.3                          | 560   | 320           | 0.3                                | 132  | 311   | 0.6                                  | 0.05                 | 3.03   | 790             |
| 627.6                          | 680   | 560           | 0.3                                | 186  | 497   | 0.7                                  | 0.06                 | 3.03   | 1310            |
| 628.0                          | 700   | 680           | 0.4                                | 276  | 773   | 1.1                                  | 0.09                 | 3.04   | 2460            |
| 629.0                          | 750   | 700           | 1.0                                | 725  | 1498  | 2.0                                  | 0.17                 | 3.06   | 6490            |
| 630.0                          | 790   | 750           | 1.0                                | 770  | 2268  | 2.9                                  | 0.24                 | 3.08   | 12,320          |
| 631.0                          | 820   | 790           | 1.0                                | 805  | 3073  | 3.7                                  | 0.31                 | 3.09   | 18,030          |
| 632.0                          | 850   | 820           | 1.0                                | 835  | 3908  | 4.6                                  | 0.38                 | 3.09   | 25,910          |
| 633.0                          | 880   | 850           | 1.0                                | 865  | 4773  | 5.4                                  | 0.45                 | 3.09   | 34,120          |
| 635.0                          | 950   | 880           | 2.0                                | 1830   | 6603  | 6.9                                  | 0.58                 | 3.09   | 53,310          |

① FROM FIELD MEASUREMENTS AND USGS TOPO

②  $A_i = H_i \left( \frac{L_1 + L_2}{2} \right)$

③  $H_w = A_T / L_1$

④  $L$  = BREADTH OF DAM = 12 FT

⑤  $C = f(H, L)$ , FROM REF 12, FIG 24

⑥  $Q = CL_1 H_w^{3/2}$

ECT DAM SAFETY INSPECTION  
LERANON DAM No. 1  
 BY DJS DATE 1-14-80 PROJ. NO. 79-203-595  
 CHKD. BY DLB DATE 1-31-80 SHEET NO. 10 OF 26



TOTAL FACILITY RATING TABLE

$$Q_{TOTAL} = Q_{SERVICE} + Q_{EMERGENCY} + Q_{EMBANKMENT}$$

| RESERVOIR<br>ELEVATION<br>(FT) | Q <sub>SERVICE</sub><br>(CFS) | Q <sub>EMERGENCY</sub><br>(CFS) | Q <sub>EMBANKMENT</sub><br>(CFS) | Q <sub>TOTAL</sub><br>(CFS) |
|--------------------------------|-------------------------------|---------------------------------|----------------------------------|-----------------------------|
| 622.5                          | 0                             | -                               | -                                | 0                           |
| 623.0                          | 10                            | 0                               | -                                | 10                          |
| 624.0                          | 50                            | 100                             | -                                | 150                         |
| 625.0                          | 110                           | 280                             | -                                | 390                         |
| (LOW TOP OF DAM) 625.3         | 130                           | 340                             | 0                                | 470                         |
| 626.0                          | 180                           | 510                             | 80                               | 770                         |
| 626.7                          | 240 *                         | 710 *                           | 320                              | 1270                        |
| 626.9                          | 250 *                         | 760 *                           | 370                              | 1380                        |
| 627.0                          | 260                           | 790                             | 450                              | 1500                        |
| 627.3                          | 290 *                         | 880 *                           | 790                              | 1960                        |
| 627.6                          | 310 *                         | 980 *                           | 1210                             | 2500                        |
| 628.0                          | 350                           | 1100                            | 2460                             | 3910                        |
| 629.0                          | 450                           | 1440                            | 6490                             | 8380                        |
| 630.0                          | 560                           | 1820                            | 12,020                           | 14,400                      |
| 631.0                          | 680                           | 2220                            | 15,030                           | 20,930                      |
| 632.0                          | 800                           | 2650                            | 25,910                           | 29,360                      |
| 633.0                          | 930                           | 3110                            | 34,120                           | 38,160                      |
| 635.0                          | 1210                          | 4090                            | 53,210                           | 58,510                      |

\* BY LINEAR INTERPOLATION

SUBJECT DAM SAFETY INSPECTION  
LEBANON DAM No. 1  
BY DJS DATE 1-15-80 PROJ. NO. 79-203-595  
CHKD. BY DLB DATE 1-31-80 SHEET NO. 11 OF 26



LEBANON DAM No. 2

DAM STATISTICS

- HEIGHT OF DAM = 49 FEET (FIELD MEASUREMENT)
- NORMAL POOL STORAGE CAPACITY = 150 ACRE-FT (SEE NOTE 1)
- MAXIMUM POOL STORAGE CAPACITY = 182 ACRE-FT (SHEET 4)
- DRAINAGE AREA = 0.6 SQUARE MILES { PLANIMETERED ON USGS TOPS:  
RICHLAND AND LEBANON, PA }
- ELEVATION OF TOP OF DAM = 679.8 (FIELD MEASUREMENT)
- NORMAL POOL ELEVATION = 676.0 (SEE NOTE 1)

NOTE 1: THESE VALUES WERE OBTAINED FROM "PHASE I INSPECTION REPORT,  
NATIONAL DAM INSPECTION PROGRAM, REXMONT No. 2 DAM", BY BERGER  
ASSOCIATES, HARRISBURG, PA, MAY, 1979.

PROJECT DAM SAFETY INSPECTION  
LEBANON DAM No. 1  
BY DTS DATE 1-15-80 PROJ. NO. 79-203-595  
CHKD. BY DLB DATE 1-31-80 SHEET NO. 12 OF 26



LEBANON DAM No. 2

DAM CLASSIFICATION

DAM SIZE : INTERMEDIATE  
HAZARD CLASSIFICATION : HIGH  
REQUIRED SDF : DMF

(SEE NOTE 1)

HYDROGRAPH PARAMETERS

LENGTH OF LONGEST WATERCOURSE :  $L = 1.10$  MILES

LENGTH OF LONGEST WATERCOURSE FROM  
DAM TO A POINT OUTSIDE BASIN CENTROID :  $LCA = 0.51$  MILES

$$C_t = 2.78$$
$$C_p = 0.82$$

SNYDER'S STANDARD LAG :  $t_p = C_t (L \cdot LCA)^{0.3}$

$$\approx 2.78 (1.1 \times 0.51)^{0.3}$$
$$\approx 2.34 \text{ HOURS}$$

(SEE NOTE 1)

RESERVOIR CAPACITY

RESERVOIR SURFACE AREAS :

- S.A @ ELEV 680 = 10.0 ACRES
- S.A @ ELEV 700 = 15.3 ACRES

PLANIMETERED ON USGS  
TOPO QUAD : RICHLAND, PA

SUBJECT DAM SAFETY INSPECTION  
LEBANON DAM No. 1  
 BY DJS DATE 1-15-80 PROJ. NO. 79-203-595  
 CHKD. BY DLB DATE 1-31-80 SHEET NO. 13 OF 26



LEBANON DAM No. 2

S.A. @ ELEV. 645 = 0.7 ACRES  
 S.A. @ ELEV 650 = 2.0 ACRES  
 S.A. @ ELEV 660 = 4.6 ACRES  
 S.A @ ELEV 676 (NORMAL POOL) = 8.3 ACRES

{ FROM PLATE III, REMOUNT  
 NO. 2 DAM, PHASE I REPORT.  
 SEE NOTE 1 }

IT IS ASSUMED THAT THE MODIFIED PRISMOIDAL RELATIONSHIP ADEQUATELY MODELS THE RESERVOIR SURFACE AREA - STORAGE RELATIONSHIP. SINCE THE CAPACITY AT NORMAL POOL IS KNOWN, THE CALCULATED VOLUMES CAN BE ADJUSTED ACCORDINGLY.

$$\Delta V_{1-2} = \frac{h}{3} (A_1 + A_2 + \sqrt{A_1 \cdot A_2}) \quad (\text{REF 14, p. 15})$$

WHERE  $\Delta V_{1-2}$  = INCREMENTAL VOLUME BETWEEN ELEVATIONS 1 & 2, IN FEET,  
 $h$  = ELEVATION 2 - ELEVATION 1, IN FEET,  
 $A_1$  = S.A. @ ELEV 1, IN ACRES,  
 $A_2$  = S.A. @ ELEV 2, IN ACRES.

IT IS ALSO ASSUMED THAT SURFACE AREA VARIES LINEARLY BETWEEN THE KNOWN VALUES GIVEN ABOVE.

ECT DAM SAFETY INSPECTION  
LEBANON DAM No. 1  
 BY DJS DATE 1-15-80 PROJ. NO. 79-203-595  
 CHKD. BY DLB DATE 1-31-80 SHEET NO. 14 OF 26



Engineers • Geologists • Planners  
 Environmental Specialists

LEBANON DAM No. 2

ELEVATION - STORAGE TABLE:

| RESERVOIR<br>ELEVATION<br>(FT) | AREA<br>(ACRES) | $\Delta V_{1-2}$<br>(AC-FT) | INITIAL CALCULATED<br>TOTAL VOLUME<br>(AC-FT) | FINAL CALCULATED<br>VOLUME **<br>(AC-FT) |
|--------------------------------|-----------------|-----------------------------|---|--|
| 640.0                          | 0               | —                           | —   | 0  |
| 645.0                          | 0.7             | 1.2                         | 1.2   | 1  |
| 650.0                          | 2.0             | 6.5                         | 7.7   | 8  |
| 655.0                          | 3.3 *           | 13.1                        | 20.8  | 22                                       |
| 660.0                          | 4.6             | 19.6                        | 40.4  | 42                                       |
| 665.0                          | 5.8 *           | 25.9                        | 66.3  | 69                                       |
| 670.0                          | 6.9 *           | 31.7                        | 98.0  | 102                                      |
| (NORMAL POOL) 676.0            | 8.3             | 45.5                        | 143.5   | 150                                      |
| 677.0                          | 8.7 *           | 8.5                         | 152.0   | 159                                      |
| 678.0                          | 9.2 *           | 8.9                         | 160.9   | 168                                      |
| 679.0                          | 9.6 *           | 9.4                         | 170.3   | 178                                      |
| (LOW TOP OF DAM) 679.8         | 9.9 *           | 7.8                         | 178.1   | 186                                      |
| 680.0                          | 10.0            | 2.0                         | 180.1   | 188                                      |
| 681.0                          | 10.3 *          | 10.1                        | 190.2   | 199                                      |
| 682.0                          | 10.5 *          | 10.4                        | 200.6   | 210                                      |
| 683.0                          | 10.8 *          | 10.6                        | 211.2   | 221                                      |
| 684.0                          | 11.1 *          | 10.9                        | 222.1   | 232                                      |
| 685.0                          | 11.3 *          | 11.2                        | 233.3   | 244                                      |

\* BY LINEAR INTERPOLATION

\*\* FINAL CALCULATED VOLUME = (INITIAL CALCULATED VOLUME) X (CORRECTION FACTOR)

$$\text{WHERE CORRECTION FACTOR} = \left( \frac{\text{KNOWN VALUE AT NORMAL POOL}}{\text{INITIAL CALC. VOL. AT NORMAL POOL}} \right)$$

$$= \frac{150}{143.5} = 1.045$$

S ECT DAM SAFETY INSPECTION

LEBANON DAM No. 1

BY DJS DATE 1-15-80 PROJ. NO. 79-203-595

CHKD. BY DLB DATE 1-31-80 SHEET NO. 15 OF 26



Engineers • Geologists • Planners  
Environmental Specialists

## LEBANON DAM No. 2

### PMP CALCULATIONS

APPROXIMATE RAINFALL INDEX IS 23.2 INCHES, CORRESPONDING TO A DURATION OF 24 HOURS AND AN AREA OF 200 SQUARE MILES, LOCATED IN SOUTHEASTERN PENNSYLVANIA.

(REF 3, FIG. 1)

- DEPTH-AREA-DURATION ZONE 6.

(REF 3, FIG. 1)

- DRAINAGE AREA = 0.6 SQUARE MILES; ASSUME DATA CORRESPONDING TO A 10-SQUARE MILE AREA IS REPRESENTATIVE OF THIS BASIN:

| <u>DURATION</u> | <u>PERCENT OF INDEX RAINFALL</u> |
|-----------------|----------------------------------|
| 6               | 113                              |
| 12              | 123                              |
| 24              | 132                              |
| 48              | 143                              |

(REF 3, FIG. 2)

HQD DROK FACTOR (ADJUSTMENT FOR BASIN SHAPE AND FOR THE LESSER LIKELIHOOD OF A SEVERE STORM CENTERING OVER A SMALL BASIN) FOR A DRAINAGE AREA OF 0.6 SQUARE MILES IS 0.80.



(REF 4, P. 48)



ECT DAM SAFETY INSPECTION  
LEBANON DAM No. 1  
 BY DJS DATE 1-16-80 PROJ. NO. 72-303-515  
 CHKD. BY DLB DATE 1-31-80 SHEET NO. 16 OF 26

**gai**  
**CONSULTANTS, INC.**  
 Engineers • Geologists • Planners  
 Environmental Specialists

## LEBANON DAM No. 2



- SECTION LOOKING UPSTREAM -

(- FROM FIELD MEASUREMENTS)

## SPILLWAY CAPACITY

THE SPILLWAY CONSISTS OF WHAT IS ESSENTIALLY A BROAD-CRESTED WEIR DISCHARGING INTO A NATURAL CHANNEL. A RATING CURVE FOR THE SPILLWAY HAS BEEN DEVELOPED (SEE NOTE 1), USING THE WEIR EQUATION,  $Q = CLH^{3/2}$ . FOR THIS WEIR, THE LENGTH,  $L$ , IS 14.5 FEET, AND THE COEFFICIENT OF DISCHARGE,  $C$ , IS 3.2. THE MINOR APPROACH LOSSES AND ENTRANCE LOSSES WERE ASSUMED TO BE INSIGNIFICANT HERE. THE BRIDGE DECK WAS ASSUMED TO BE

S. ECT DAM SAFETY INSPECTION  
LEBANON DAM No. 1  
 BY DJS DATE 1-16-80 PROJ. NO. 79-203-595  
 CHKD. BY D.L.G. DATE 1-31-80 SHEET NO. 17 OF 26



## LEBANON DAM No. 2

WASHED OUT UNDER HIGH FLOWS, AND THE STEEL SUPPORT BEAMS WERE ASSUMED TO HAVE NEGLIGIBLE EFFECTS ON DISCHARGE.

### SPILLWAY RATING TABLE:

| RESERVOIR<br>ELEVATION<br>(FT) | H<br>(FT) | Q <sup>*</sup><br>(CFS) | RESERVOIR<br>ELEVATION<br>(FT) | H<br>(FT) | Q <sup>*</sup><br>(CFS) |
|--------------------------------|-----------|-------------------------|--------------------------------|-----------|-------------------------|
| 676.0                          | 0         | 0                       | 681.0                          | 5.0       | 530                     |
| 677.0                          | 1.0       | 50                      | 682.0                          | 6.0       | 630                     |
| 678.0                          | 2.0       | 130                     | 683.0                          | 7.0       | 860                     |
| 679.0                          | 3.0       | 240                     | 684.0                          | 8.0       | 1050                    |
| 679.5                          | 3.5       | 340                     | 685.0                          | 9.0       | 1250                    |
| 680.0                          | 4.0       | 370                     |                                |           |                         |

\*  $Q = CLH^{3/2}$ ,  $L = 14.5$ ,  $C = 3.2$

### EMBANKMENT RATING CURVE

ASSUME THAT THE EMBANKMENT BEHAVES ESSENTIALLY AS A BROAD-CRESTED WEIR UPON OVERTOPPING. THUS, THE DISCHARGE CAN BE ESTIMATED BY THE RELATION

$$Q = CLH^{3/2} \quad (\text{REF 5, p. 5-23})$$

WHERE

Q = DISCHARGE OVER EMBANKMENT, IN CFS,  
 L = LENGTH OF EMBANKMENT OVERTOPPED, IN FEET,  
 H = HEAD ON WEIR; IN THIS CASE, IT IS THE AVERAGE "FLOW-AREA"  
 WEIGHTED HEAD ALONG THE CREST (LOW TOP OF DAM),  
 C = COEFFICIENT OF DISCHARGE; DEPENDENT ON THE HEAD AND  
 THE WEIR BREADTH.

ECT DAM SAFETY INSPECTION  
LEBANON DAM No. 1  
 BY DJS DATE 1-16-80 PROJ. NO. 79-303-595  
 CHKD. BY DLG DATE 1-31-80 SHEET NO. 18 OF 26



Engineers • Geologists • Planners  
 Environmental Specialists

### LEBANON DAM No. 2

ASSUME THAT INCREMENTAL DISCHARGES FOR SUCCESSIVE RESERVOIR ELEVATIONS ARE APPROXIMATELY TRAPEZOIDAL IN CROSS-SECTIONAL FLOW AREA. THEN ANY INCREMENTAL AREA OF FLOW (BETWEEN SPECIFIED RESERVOIR ELEVATIONS) IS APPROXIMATELY EQUAL TO  $H_i [(L_1 + L_2)/2]$ , WHERE  $L_1$  = LENGTH OF OVERTOPPED EMBANKMENT AT HIGHER ELEVATION,  $L_2$  = LENGTH AT LOWER ELEVATION,  $H_i$  = ELEVATION DIFFERENCE. THUS, THE TOTAL AVERAGE "FLOW-AREA" WEIGHTED HEAD,  $H_w$ , IS APPROXIMATELY EQUAL TO (TOTAL FLOW AREA /  $L_1$ ).

EMBANKMENT RATING TABLE:

| ①<br>RESERVOIR<br>ELEVATION<br>(FT) | ②<br>LENGTH<br>OVERTOPPED,<br>$L_1$<br>(FT) | $L_2$<br>(FT) | INCREMENTAL<br>HEAD, $H_i$<br>(FT) | INCREMENTAL<br>AREA, $A_i$<br>(FT <sup>2</sup> ) | TOTAL FLOW<br>AREA, $A_T$<br>(FT <sup>2</sup> ) | ③<br>WEIGHTED<br>HEAD, $H_w$<br>(FT) | ④<br>$\frac{H_w}{L}$ | ⑤<br>C | ⑥<br>Q<br>(CFS) |
|-------------------------------------|---|---------------|------------------------------------|--|---|--------------------------------------|----------------------|--------|-----------------|
| 679.8                               | 0   | 0             | 0                                  | 0  | 0   | 0                                    | —                    | —      | 0               |
| 679.9                               | 350   | 0             | 0.1                                | 18   | 18  | 0.1                                  | 0.01                 | 2.93   | 30              |
| 680.0                               | 430   | 350           | 0.1                                | 39   | 57  | 0.1                                  | 0.01                 | 2.93   | 40              |
| 680.2                               | 640   | 430           | 0.2                                | 107  | 164   | 0.3                                  | 0.02                 | 2.99   | 310             |
| 680.5                               | 730   | 640           | 0.3                                | 206  | 370   | 0.5                                  | 0.03                 | 3.02   | 780             |
| 681.0                               | 740   | 730           | 0.5                                | 368  | 738   | 1.0                                  | 0.06                 | 3.03   | 2240            |
| 682.0                               | 750   | 740           | 1.0                                | 745  | 1483  | 2.0                                  | 0.12                 | 3.04   | 6450            |
| 683.0                               | 770   | 750           | 1.0                                | 760  | 2243  | 2.9                                  | 0.17                 | 3.06   | 11,640          |
| 684.0                               | 780   | 770           | 1.0                                | 775  | 3018  | 3.9                                  | 0.23                 | 3.08   | 18,500          |
| 685.0                               | 790   | 780           | 1.0                                | 785  | 3803  | 4.8                                  | 0.28                 | 3.09   | 25,670          |

- ① FROM FIELD MEASUREMENTS AND USGS TOPO
- ②  $A_i = H_i [(L_1 + L_2)/2]$
- ③  $H_w = A_T / L_1$
- ④  $L$  = BROADTH OF CREST = 17 FT (AVG.)
- ⑤  $C = f(H, L)$ , FROM REF 12, FIG. 24
- ⑥  $Q = CL_1 H_w^{3/2}$

SUBJECT DAM SAFETY INSPECTION  
LEBANON DAM No. 1  
 BY DJS DATE 1-16-80 PROJ. NO. 79-203-595  
 CHKD. BY DLB DATE 1-31-80 SHEET NO. 19 OF 26



LEBANON DAM No. 2


TOTAL FACILITY RATING TABLE

$$Q_{TOTAL} = Q_{SPILLWAY} + Q_{EMBANKMENT}$$

|                     | RESERVOIR<br>ELEVATION | $Q_{SPILLWAY}$ | $Q_{EMBANKMENT}$ | $Q_{TOTAL}$ |
|---------------------|------------------------|----------------|------------------|-------------|
|                     | 676.0                  | 0              | -                | 0           |
|                     | 677.0                  | 50             | -                | 50          |
|                     | 678.0                  | 130            | -                | 130         |
|                     | 679.0                  | 240            | -                | 240         |
| (LOW TOP<br>OF DAM) | 679.8                  | 340            | 0                | 340         |
|                     | 679.9                  | 360 *          | 30               | 390         |
|                     | 680.0                  | 370            | 40               | 410         |
|                     | 680.2                  | 400 *          | 310              | 710         |
|                     | 680.5                  | 450 *          | 780              | 1230        |
|                     | 681.0                  | 520            | 2240             | 2760        |
|                     | 682.0                  | 680            | 6450             | 7130        |
|                     | 683.0                  | 860            | 11,640           | 12,500      |
|                     | 684.0                  | 1050           | 18,500           | 19,550      |
|                     | 685.0                  | 1250           | 25,670           | 26,920      |


\* BY LINEAR INTERPOLATION


DOWNSTREAM ROUTING SECTIONS



SEVERAL TIMES TO THE POINT  
FROM 1978 TO 1980  
AND OBSERVATIONS AND DATA  
FROM RICHMOND, PA.

CROSS-SECTION 2.0  
ELEVATION 15  
OF RIVER  
CHANNEL  
WIDTH 100 FT  
DEPTH 10 FT  
AREA 1000 SQ FT  
PERIMETER 140 FT  
WETTED PERIMETER 120 FT






PROJECT DAM SAFETY INSPECTION  
LERANON DAM No. 1  
 BY DES DATE 1-29-80 PROJ. NO. 79-203-595  
 CHKD. BY DLB DATE 2-1-80 SHEET NO. 23 OF 26

**gai**  
 CONSULTANTS, INC.  
 Engineers • Geologists • Planners  
 Environmental Specialists

### BREACH ASSUMPTIONS

#### TYPICAL BREACH SECTION:



#### HEC-1 DAM BREACHING ANALYSIS INPUT:

| <u>PLAN</u>                    | <u>DAM No. 1</u>                |                          |                           |                           | <u>DAM No. 2</u>                |                          |                           |                           |
|--------------------------------|---------------------------------|--------------------------|---------------------------|---------------------------|---------------------------------|--------------------------|---------------------------|---------------------------|
|                                | <u>BREACH BOTTOM WIDTH (FT)</u> | <u>BREACH DEPTH (FT)</u> | <u>SECTION SIDESLOPES</u> | <u>BREACH* TIME (HRS)</u> | <u>BREACH BOTTOM WIDTH (FT)</u> | <u>BREACH DEPTH (FT)</u> | <u>SECTION SIDESLOPES</u> | <u>BREACH* TIME (HRS)</u> |
| ① MIN. SECTION, MIN. FAIL TIME | 0                               | 22                       | 1:1                       | 0.5                       | 0                               | 40                       | 1/3:1                     | 0.5                       |
| ② MAX. SECTION, MIN. FAIL TIME | 300                             | 22                       | 8:1                       | 0.5                       | 300                             | 40                       | 5:1                       | 0.5                       |
| ③ MIN. SECTION MAX. FAIL TIME  | 0                               | 22                       | 1:1                       | 4.0                       | 0                               | 40                       | 1/3:1                     | 4.0                       |
| ④ MAX. SECTION MAX. FAIL TIME  | 300                             | 22                       | 8:1                       | 4.0                       | 300                             | 40                       | 5:1                       | 4.0                       |
| ⑤ AVERAGE POSSIBLE CONDITIONS  | 75                              | 22                       | 2:1                       | 2.0                       | 100                             | 40                       | 1:1                       | 2.0                       |

\* BREACH TIME IS THE TOTAL TIME NEEDED TO REACH FINAL BREACH DIMENSIONS.



PROJECT DAM SAFETY INSPECTION  
LERANON DAM NO. 1  
 BY DJS DATE 1-29-80 PROJ. NO. 79-303-595  
 CHKD. BY DLB DATE 2-1-80 SHEET NO. 24 OF 26



THE BREACH ASSUMPTIONS LISTED ON SHEET 23 ARE BASED SOMEWHAT ON INFORMATION CONCERNING EARTH DAM BREACHING PROVIDED BY THE C.O.E., BALTIMORE DISTRICT, AND ON THE PHYSICAL CONSTRAINTS OF THE DAM AND SURROUNDING TERRAIN.

DAM NO. 1: (DOWNSTREAM DAM)

- MAX. DEPTH OF BREACH = TOP OF DAM - ZERO STORAGE ELEV (SHEET 3)  
 $= 625 - 603 = \underline{22}$  FEET
- LENGTH OF BREACHABLE EMBANKMENT = 650 FT
- VALLEY BOTTOM WIDTH = 300 FT
- SIDE SLOPES: AVG. = 8:1  
 (BASED ON RESERVOIR AND VALLEY GEOMETRY)

DAM NO. 2: (UPSTREAM DAM)

- MAX. DEPTH OF BREACH = TOP OF DAM - MIN. RESERVOIR ELEV  
 $= 679.8 - 640 = \underline{40}$  FT
- LENGTH OF BREACHABLE EMBANKMENT = 720 FT
- VALLEY BOTTOM WIDTH = 300 FT
- SIDE SLOPES: AVG. = 5:1  
 (BASED ON RESERVOIR AND VALLEY GEOMETRY)

NOTE: THE CONSTRAINTS LISTED ABOVE ARE TAKEN FROM FIELD NOTES AND OBSERVATIONS, FROM USGS TOPO, RICHLAND, PA, AND FROM FIGURE 3. THE BREACHABLE EMBANKMENT LENGTHS DO NOT INCLUDE SPILLWAY CREST LENGTHS.

ECT DAM SAFETY INSPECTIONLEBANON DAM No. 1BY 225 DATE 1-4-80 PROJ. NO. 79-203-595CHKD. BY DLB DATE 2-14-80 SHEET NO. 25 OF 26Engineers • Geologists • Planners  
Environmental SpecialistsHEC-1 DAM BREACHING ANALYSIS OUTPUTRESERVOIR DATA:UNDER 0.24 PMF BASE FLOW CONDITIONS:

| RESERVOIR   | PLAN NUMBER | RESERVOIR NO. 2 | RESERVOIR NO. 1 | WIDTH (FT) | ACTUAL MAXIMUM FLOW DURING FAILURE (CFS) | CORRESPONDING TIME OF FLOW (HRS) | INTERPOLATED OR HEC-1 ROUTED MAX FLOW DURING FAILURE (CFS) | CORRESPONDING TIME OF FLOW (HRS) | ACTUAL PEAK FLOW THROUGH DAM (CFS) | CORRESPONDING TIME OF FLOW (HRS) | TIME OF INITIAL BREACH (HRS) |
|-------------|-------------|-----------------|-----------------|------------|--|----------------------------------|--|----------------------------------|------------------------------------|----------------------------------|------------------------------|
| LEBANON # 2 | ①           | 0               | —               | —          | 5887                                     | 42.33                            | 5887   | 42.33                            | 5887                               | 42.33                            | 41.83                        |
|             | ②           | 300             | —               | —          | 8125                                     | 42.00                            | 8125   | 42.00                            | 8125                               | 42.00                            | 41.83                        |
|             | ③           | 0               | —               | —          | 1074                                     | 44.33                            | 1074   | 44.33                            | 1074                               | 44.33                            | 41.83                        |
|             | ④           | 300             | —               | —          | 1512                                     | 42.17                            | 1512   | 42.17                            | 1512                               | 42.17                            | 41.83                        |
|             | ⑤           | 100             | —               | —          | 2338                                     | 42.29                            | 2338   | 42.33                            | 2338                               | 42.29                            | 41.83                        |
| LEBANON # 1 | ①           | 0               | 0               | 0          | 3412                                     | 41.83                            | 3412   | 41.83                            | 4333                               | 42.50                            | 41.33                        |
|             | ②           | 300             | 300             | 300        | 4980                                     | 41.47                            | 4810   | 41.50                            | 8375                               | 42.00                            | 41.33                        |
|             | ③           | 0               | 0               | 0          | 1509                                     | 44.50                            | 1809   | 44.50                            | 1809                               | 44.50                            | 41.33                        |
|             | ④           | 300             | 300             | 300        | 2398                                     | 42.25                            | 2361   | 42.17                            | 2398                               | 42.25                            | 41.33                        |
|             | ⑤           | 100             | 75              | 75         | 3518                                     | 42.33                            | 3518   | 42.33                            | 3518                               | 42.33                            | 41.33                        |

ECT DAM SAFETY INSPECTION

LEBANON DAM No. 1

BY RTS DATE 1-4-80 PROJ. NO. 79-203-595

CHKD. BY DLB DATE 2-14-80 SHEET NO. 26 OF 26



# HEC-1 DAM BREACHING ANALYSIS OUTPUT:

## DOWNSTREAM ROUTING DATA:

UNDER 0.24 PMF BASE FLOW CONDITIONS:

| VARIABLE BREACH<br>BOTTOM WIDTH (FT)<br>RES. # 2 RES. # 1 | OUTPUT AT SECTION 3, LOCATED<br>2100 FT D.S. FROM DAM #1 |                                |                                | OUTPUT AT SECTION 4, LOCATED<br>1050 FT D.S. FROM DAM #1 |                                |                                | OUTPUT AT SECTION 5, LOCATED<br>8450 FT D.S. FROM DAM #1 |                                |                                |
|---|--|--------------------------------|--------------------------------|--|--------------------------------|--------------------------------|--|--------------------------------|--------------------------------|
|   | PEAK<br>FLOW<br>(CFS)                                    | WSEL (2)<br>W/O BREACH<br>(FT) | WSEL (3)<br>W/O BREACH<br>(FT) | PEAK<br>FLOW<br>(CFS)                                    | WSEL (2)<br>W/O BREACH<br>(FT) | WSEL (3)<br>W/O BREACH<br>(FT) | PEAK<br>FLOW<br>(CFS)                                    | WSEL (2)<br>W/O BREACH<br>(FT) | WSEL (3)<br>W/O BREACH<br>(FT) |
| ① 0 0   | 3979   | 545.8                          | 544.3 +1.5                     | 3514   | 532.2                          | 530.4 +1.8                     | 3410   | 506.9                          | 503.9 +3.0                     |
| ② 300 300   | 6417   | 546.4                          | 544.3 +2.1                     | 4795   | 532.6                          | 530.4 +2.2                     | 4194   | 507.5                          | 503.9 +3.6                     |
| ③ 0 0   | 1793   | 545.1                          | 544.3 +0.8                     | 1772   | 531.3                          | 530.4 +0.9                     | 1758   | 505.6                          | 503.9 +1.7                     |
| ④ 300 300   | 2294   | 545.2                          | 544.3 +0.9                     | 2224   | 531.6                          | 530.4 +1.2                     | 2180   | 505.9                          | 503.9 +2.0                     |
| ⑤ 100 75  | 3427   | 545.6                          | 544.3 +1.3                     | 3228   | 532.1                          | 530.4 +1.7                     | 3151   | 506.7                          | 503.9 +2.8                     |

- (1) SEE TABLE, SHEET 14
- (2) WATER SURFACE ELEVATIONS CORRESPONDING TO BREACH OUTFLOWS (SUMMARY INLET/OUTLET SHEETS, SHEETS U, V)
- (3) BASE FLOW ELEVATIONS CORRESPONDING TO THE PEAK 0.24 PMF AS INTERPOLATED FROM SHEET M, SUMMARY Inlet/Outlet Sheets.
- (4) ELEVATION (CORRESPONDING WSEL) - (WSEL W/O BREACH)



**Engineers • Geologists • Planners  
Environmental Specialists**

## OVERTOPPING ANALYSIS

DAM SAFETY INSPECTION  
LEBANON DAM NO. 1 W/U.S. LEBANON DAM NO. 2 \*\*\* OVERTOPPING ANALYSIS \*\*\*  
15-MINUTE TIME STEP AND 48-HOUR STORM DURATION

| NO  | MNR | MMIN | DAY   | JOB SPECIFICATION | IPRI | INSTAN |
|-----|-----|------|-------|-------------------|------|--------|
| 288 | 0   | 10   | 0     | INR ININ METNC    | 0    | 0      |
|     |     |      | JUPER | NMT LROPT THACE   |      |        |
|     |     |      | 5     | 0 0 0             |      |        |

MULTI-PLAN ANALYSES TO BE PERFORMED  
 MPLANS: 1 NRTO: 5 LRTO: 1

| PRICE | 10 | 20 | 30 | 50 | 1.00 |
|-------|----|----|----|----|------|
| 10    |    |    |    |    |      |
| 20    |    |    |    |    |      |
| 30    |    |    |    |    |      |
| 50    |    |    |    |    |      |
| 1.00  |    |    |    |    |      |

[illegible]

SUB-AREA RUNOFF COMPUTATION

| ISTAU | ICOMP | IECON | ITAPE | JPL1 | JPRE | INAME | ISTAGE | IAUTO |
|-------|-------|-------|-------|------|------|-------|--------|-------|
| AM 27 | 0     | 0     | 0     | 0    | 0    | 1     | 0      | 0     |

## HYDROSCOPIC DATA

|       | ISNAME | ISNUM | RATIO | TRSPC | SHAP | TAREA | IUNG | THUNG |
|-------|--------|-------|-------|-------|------|-------|------|-------|
| LOCAL | 0      | 0     | 0.000 | 0.00  | 0.00 | 0.00  | 0.   | 0.    |

### PRECIP DATA

| SPFL  | PMS   | R6    | R12   | R24   | K48    | K72  | K96  |
|-------|-------|-------|-------|-------|--------|------|------|
| 33.30 | 11.30 | 12.30 | 13.00 | 13.00 | 143.00 | 0.00 | 0.00 |

```

TRANSPC COMPUTED BY THE PROGRAM IS .800
0.00 23.20 115.00 122.00 122.00 122.00
INITIAL AND CONSTANT
RAINFALL LOSSES (C.O.E.)

```

[illegible]UNIT HYDROGRAPH DATA  
7-14 C/E M7 N/A=0  
10-  
10-  
POTENTIAL PROBLEMS

РАЗРАБОТКА  
(с. 9, 10)

```

RECESSION DATA
SINT02 = -1.50  ORC502 = -.05  N10UH = 1.00
C10H SHOULD BE AND 10 ARE TC310.06 AND N2 5.52 INTERVALS

```

| UNIT HYDROGRAPH | 41 END-OF-PERIOD ORIGINATED, IAGS | 2.34 HOURS, CPZ | .81  | VALUE 1.00 |
|-----------------|-----------------------------------|-----------------|------|------------|
| 3.              | 12.                               | 37.             | 51.  | 64.        |
| 26.             | 133.                              | 139.            | 138. | 134.       |
| 79.             | 60.                               | 55.             | 38.  | 27.        |
| 11.             | 9.                                | 7.              | 6.   | 5.         |
| 2.              |                                   |                 |      |            |
|                 |                                   |                 |      | 91.        |
|                 |                                   |                 |      | 74.        |
|                 |                                   |                 |      | 129.       |
|                 |                                   |                 |      | 22.        |
|                 |                                   |                 |      | 4.         |
|                 |                                   |                 |      | 9.         |
|                 |                                   |                 |      | 3.         |
|                 |                                   |                 |      | 104.       |
|                 |                                   |                 |      | 110.       |
|                 |                                   |                 |      | 95.        |
|                 |                                   |                 |      | 15.        |
|                 |                                   |                 |      | 14.        |
|                 |                                   |                 |      | 3.         |

| NO.DA | H.M.NN | PERIOD | RAIN | LICS | LUSS | CUMP U | FLOW<br>MU.DA | M.R.MM | PENIUD | RAIN    | E.XCS  | LUSS       | CUMP U |
|-------|--------|--------|------|------|------|--------|---------------|--------|--------|---------|--------|------------|--------|
|       |        |        |      |      |      |        |               |        | SUM    | ( 674.) | ( 61.) | ( 1082.10) |        |
|       |        |        |      |      |      |        |               |        |        | 26.54   | 24.13  | 2.41       | 55185. |

# DAM SAFETY INSPECTION

LEBANON DAM No. 1

BY DJS

DATE \_\_\_\_\_

ब-12-४८

**PROJ. NO.**

79-203-595


CHKD. BY DLB

DATE \_\_\_\_\_

2-14-80

**SHEET NO**

B OF 2



CONSULTANTS, INC.

**Engineers • Geologists • Planners  
Environmental Specialists**

|        | 178. | 120.  | 37.   | 19.   | 5515. |
|--------|------|-------|-------|-------|-------|
| (FS    |      |       |       |       |       |
| GMS    | 5.   | 3.    | 1.    | 1.    | 156.  |
| INCHES |      | 1.85  | 2.29  | 2.31  |       |
| MM     |      | 47.03 | 58.70 | 60.32 |       |
| AC-FT  |      | 59.   | 73.   | 76.   |       |
|        |      | 71.   | 90.   | 94.   |       |

| PEAK       | 6-HOUR | 24-HOUR | 72-HOUR | TOTAL  | VOLUME |
|------------|--------|---------|---------|--------|--------|
| CFS        | 239.   | 74.     | 38.     | 11029. |        |
| CMS        | 7.     | 2.      |         | 312.   |        |
| INCHES     | 3.71   | 4.58    | 4.75    |        |        |
| MM         | 94.15  | 116.40  | 120.65  |        |        |
| AC-FT      | 119.   | 147.    | 152.    |        |        |
| MINUS CU M | 146.   | 181.    | 187.    |        |        |

| PEAK       | 6-HOUR | 24-HOUR | 72-HOUR | TOTAL VOLUME |
|------------|--------|---------|---------|--------------|
| CFS        | 336.   | 111.    | 57.     | 16549.       |
| CMS        | 15.    | 10.     | 7.      | 468.         |
| INCHES     | 5.56   | 6.87    | 7.12    |              |
| MM         | 141.22 | 174.60  | 180.97  |              |
| AC-FT      | 178.   | 220.    | 228.    |              |
| THOUS CU M | 219.   | 271.    | 281.    |              |

| PEAK | 0-HOUR | 24-HOUR | 72-HOUR | TOTAL VOLUME |
|------|--------|---------|---------|--------------|
| 990. | 545.   | 142.    | 90.     | 27573.       |
| 25.  | 11.    | 5.      | 1.      | 781.         |
|      | 9.47   | 11.46   | 11.87   | 11.07        |
|      | 235.36 | 291.00  | 301.82  | 301.62       |
|      | 296.   | 366.    | 380.    | 380.         |
|      | 366.   |         | 403.    | 403.         |

|            | PEAK  | 6-HOUR | 24-HOUR | 72-HOUR | TOTAL  |
|------------|-------|--------|---------|---------|--------|
| CFS        | 1781. | 1195.  | 389.    | 191.    | 53146. |
| CMS        | 50.   | 34.    | 10.     | 5.      | 1562.  |
| INCHES     |       | 18.53  | 22.91   | 23.75   | 2352.  |
| MM         |       | 470.73 | 582.00  | 603.24  | 603.24 |
| AC-FT      |       | 593.   | 733.    | 760.    | 760.   |
| FOCUS CU M |       | 931.   | 904.    | 937.    | 937.   |

100

## HYDROGRAPH ROUTING

## MINUTE THROUGH RESERVOIR

[illegible]

**gai**  
**CONSULTANTS, INC.**  
Engineers • Geologists • Planners  
Environmental Specialists

0.1 PMF

## 0.2 PMF

0.3 PMF

[illegible]

|       |          |      |        |
|-------|----------|------|--------|
| RUPEL | DAM DATA |      | DAMWID |
| 679.8 | CUQD     | EXPU |        |
|       | 0.0      | 0.0  | 0.     |

PEAK OUTFLOW IS 151. AT TIME 42.67 HOURS

|            | PEAK | 6-HOUR | 24-HOUR | 72-HOUR | TOTAL | VOLUME |
|------------|------|--------|---------|---------|-------|--------|
| CFS        | 151. | 100.   | 35.     | 10.     |       | 5197.  |
| CMS        | 3.   |        | 1.      | 1.      |       | 147.   |
| INCHES     | 4.   | 1.67   | 2.16    | 2.23    |       | 2.23   |
| MM         |      | 42.26  | 54.85   | 56.74   |       | 56.74  |
| AC-FT      |      | 53.    | 59.     | 71.     |       | 71.    |
| THOUS CU M |      | 66.    | 85.     | 88.     |       | 88.    |

PEAK OUTFLOW IS 317. AT TIME 42.67 HOURS

|            | PEAK  | 6-HOUR | 24-HOUR | 72-HOUR | TOTAL | VOLUME |
|------------|-------|--------|---------|---------|-------|--------|
| CFS        | 317.  | 222.   | 71.     | 37.     |       | 10530. |
| CMS        | 9.    | 6.     | 2.      | 1.      |       | 298.   |
| INCHES     | 3.45  | 4.39   | 4.53    | 4.53    |       | 4.53   |
| MM         | 87.55 | 111.41 | 115.19  | 115.19  |       | 115.19 |
| AC-FT      | 110.  | 140.   | 145.    | 145.    |       | 145.   |
| THOUS CU M | 136.  | 173.   | 179.    | 179.    |       | 179.   |

PEAK OUTFLOW IS 533. AT TIME 41.83 HOURS

|            | PEAK | 6-HOUR | 24-HOUR | 72-HOUR | TOTAL VOLUME |
|------------|------|--------|---------|---------|--------------|
| CFS        | 533. | 340.   | 107.    | 55.     | 15934.       |
| CMS        | 15.  | 10.    | 3.      | 1.      | 451.         |
| INCHES     |      | 5.27   | 6.64    | 6.86    | 6.86         |
| MM         |      | 133.76 | 169.62  | 174.29  | 174.29       |
| AC-FT      |      | 108.   | 212.    | 108.    | 219.         |
| THOUS CU M |      | 208.   | 262.    | 271.    | 271.         |

LEBANON  
DAM NO.2  
OUTFLOW  
HYDROGRAPHS

SUBJECT DAM SAFETY INSPECTION  
LEBANON DAM NO. 1  
 BY DJS DATE 2-12-80 PROJ. NO. 79-203-595  
 CHKD. BY DLB DATE 2-14-80 SHEET NO. D OF V



LEBANON  
DAM NO. 2  
OUTFLOW  
HYDROGRAPHS

0.5 PMF

PMF

PEAK OUTFLOW IS 889. AT TIME 41.83 HOURS

| PEAK       | 6-HOUR | 24-HOUR | 72-HOUR | TOTAL VOLUME |
|------------|--------|---------|---------|--------------|
| 989.       | 578.   | 180.    | 93.     | 26783.       |
| 25.        | 16.    | 5.      | 3.      | 758.         |
| CFS        | 8.96   | 11.16   | 11.53   | 11.53        |
| CMS        | 227.52 | 283.53  | 292.98  | 292.98       |
| INCHES     | 286.   | 357.    | 369.    | 369.         |
| MM         | 353.   | 440.    | 455.    | 455.         |
| AC-FT      |        |         |         |              |
| THOUS CU M |        |         |         |              |

PEAK OUTFLOW IS 1780. AT TIME 41.83 HOURS

| PEAK       | 6-HOUR | 24-HOUR | 72-HOUR | TOTAL VOLUME |
|------------|--------|---------|---------|--------------|
| 1780.      | 1190.  | 363.    | 188.    | 54039.       |
| 50.        | 34.    | 10.     | 5.      | 1536.        |
| CFS        | 18.45  | 22.53   | 23.27   | 23.27        |
| CMS        | 468.70 | 572.15  | 591.13  | 591.13       |
| INCHES     | 590.   | 720.    | 744.    | 744.         |
| MM         | 728.   | 889.    | 918.    | 918.         |
| AC-FT      |        |         |         |              |
| THOUS CU M |        |         |         |              |

RESERVOIR INFLOW - LEBANON DAM NO. 1 RESERVOIR

SUB-AREA RUNOFF COMPUTATION

| ISTAU | ICOMP | ISCON | ITAVE | JPLT | JPMI | ISAGE | LAUCL |
|-------|-------|-------|-------|------|------|-------|-------|
| AM #1 | 0     | 0     | 0     | 0    | 1    | 0     | 0     |

HYDROGRAPH DATA

| INYDC | 1UNG | TAREA | SNAP | TRSDA | TRSPC | RATIO | ISNUM | ISAME | LOCAL |
|-------|------|-------|------|-------|-------|-------|-------|-------|-------|
| 1     | 1    | .60   | 0.00 | 1.20  | 0.00  | 0.000 | 0     | 1     | 0     |

PRECIP DATA

| SPFE | PMS   | R6     | R12    | R24    | R48    | R72  | R96  |
|------|-------|--------|--------|--------|--------|------|------|
| 0.00 | 23.20 | 113.00 | 123.00 | 132.00 | 143.00 | 0.00 | 0.00 |

LOSS DATA

| LRUP1 | STKR1 | DLTR1 | HTIOL | ERAIN | STIRKS | HTIOK | STIRL | CNSTL | ALSMX | RTIMP |
|-------|-------|-------|-------|-------|--------|-------|-------|-------|-------|-------|
| 0     | 0.00  | 0.00  | 1.00  | 0.00  | 0.00   | 1.00  | 1.00  | .05   | 0.00  | 0.00  |

UNIT HYDROGRAPH DATA

TP= 3.47 CP= .82 NFA= 0

RECESSION DATA

SINUS -1.50 URCSM= -.05 RTIUM= 4.00

APPROXIMATE CLARK COEFFICIENTS FROM GIVEN SNIDER CP AND TP ARE TC=28.07 AND N= 7.96 INTERVALS

UNIT HYDROGRAPH 59 END-ON-PERIOD UNDIMINISHED, LAG= 3.44 HOURS, CP= .81 WUL= 1.00

| 1.  | 5.  | 10. | 15. | 20. | 25. | 30. | 35. | 40. | 45.  | 50.  |
|-----|-----|-----|-----|-----|-----|-----|-----|-----|------|------|
| 59. | 65. | 71. | 77. | 82. | 86. | 90. | 94. | 98. | 102. | 106. |
| 54. | 46. | 40. | 36. | 31. | 28. | 24. | 21. | 19. | 17.  | 15.  |
| 15. | 13. | 11. | 10. | 9.  | 8.  | 7.  | 6.  | 5.  | 4.   | 3.   |



**GNI**  
CONSULTANTS, INC.  
Engineers • Geologists • Planners  
Environmental Specialists

[illegible]



PROJECT DAM SAFETY INSPECTION  
LEBANON DAM No. 1  
 BY DJS DATE 2-12-80 PROJ. NO. 79-203-595  
 CHKD. BY DLB DATE 2-14-80 SHEET NO. F OF V



|   |        |         |         |              |      |       |        |       |  |
|---|--------|---------|---------|--------------|------|-------|--------|-------|--|
| COMBINE RESERVOIR #2 ROUTED HYDROGRAPH WITH RES. #1 INFLOW HYDROGRAPH |        |         |         |              |      |       |        |       |  |
| CUMULATIVE HYDROGRAPHS  |        |         |         |              |      |       |        |       |  |
| ISTAQ   | ICUMP  | ICUM    | ITAPE   | JPLI         | JPHI | INAME | ISTAGE | IAUTO |  |
| 1   | 2      | 0       | 0       | 0            | 0    | 1     | 0      | 0     |  |
| 0.1 PMF   |        |         |         |              |      |       |        |       |  |
| PEAK  | 6-HOUR | 24-HOUR | 72-HOUR | TOTAL VOLUME |      |       |        |       |  |
| 298.  | 219.   | 71.     | 37.     | 10603.       |      |       |        |       |  |
| 8.  | 6.     | 2.      | 1.      | 306.         |      |       |        |       |  |
| CFS   | 1.70   | 2.21    | 2.28    | 2.28         |      |       |        |       |  |
| CMS   | 43.10  | 56.02   | 57.99   | 57.99        |      |       |        |       |  |
| INCHES  | 109.   | 141.    | 146.    | 146.         |      |       |        |       |  |
| MM  | 134.   | 174.    | 180.    | 180.         |      |       |        |       |  |
| AC-FT   |        |         |         |              |      |       |        |       |  |
| THOUS CU M  |        |         |         |              |      |       |        |       |  |
| 0.2 PMF   |        |         |         |              |      |       |        |       |  |
| PEAK  | 6-HOUR | 24-HOUR | 72-HOUR | TOTAL VOLUME |      |       |        |       |  |
| 611.  | 445.   | 143.    | 74.     | 21362.       |      |       |        |       |  |
| 17.   | 13.    | 4.      | 2.      | 605.         |      |       |        |       |  |
| CFS   | 3.45   | 4.44    | 4.60    | 4.60         |      |       |        |       |  |
| CMS   | 87.69  | 112.89  | 116.84  | 116.84       |      |       |        |       |  |
| INCHES  | 221.   | 284.    | 294.    | 294.         |      |       |        |       |  |
| MM  | 272.   | 351.    | 363.    | 363.         |      |       |        |       |  |
| AC-FT   |        |         |         |              |      |       |        |       |  |
| THOUS CU M  |        |         |         |              |      |       |        |       |  |
| 0.3 PMF   |        |         |         |              |      |       |        |       |  |
| PEAK  | 6-HOUR | 24-HOUR | 72-HOUR | TOTAL VOLUME |      |       |        |       |  |
| 955.  | 674.   | 216.    | 112.    | 32181.       |      |       |        |       |  |
| 27.   | 19.    | 6.      | 3.      | 911.         |      |       |        |       |  |
| CFS   | 5.23   | 6.70    | 6.93    | 6.93         |      |       |        |       |  |
| CMS   | 132.78 | 170.09  | 176.01  | 176.01       |      |       |        |       |  |
| INCHES  | 334.   | 428.    | 443.    | 443.         |      |       |        |       |  |
| MM  | 412.   | 528.    | 547.    | 547.         |      |       |        |       |  |
| AC-FT   |        |         |         |              |      |       |        |       |  |
| THOUS CU M  |        |         |         |              |      |       |        |       |  |
| 0.5 PMF   |        |         |         |              |      |       |        |       |  |
| PEAK  | 6-HOUR | 24-HOUR | 72-HOUR | TOTAL VOLUME |      |       |        |       |  |
| 1591.   | 1134.  | 382.    | 187.    | 53863.       |      |       |        |       |  |
| 45.   | 32.    | 10.     | 5.      | 1525.        |      |       |        |       |  |
| CFS   | 9.79   | 11.21   | 11.60   | 11.60        |      |       |        |       |  |
| CMS   | 223.28 | 284.72  | 294.60  | 294.60       |      |       |        |       |  |
| INCHES  | 562.   | 717.    | 742.    | 742.         |      |       |        |       |  |
| MM  | 694.   | 884.    | 915.    | 915.         |      |       |        |       |  |
| AC-FT   |        |         |         |              |      |       |        |       |  |
| THOUS CU M  |        |         |         |              |      |       |        |       |  |
| PMF   |        |         |         |              |      |       |        |       |  |
| PEAK  | 6-HOUR | 24-HOUR | 72-HOUR | TOTAL VOLUME |      |       |        |       |  |
| 3176.   | 2279.  | 726.    | 376.    | 108198.      |      |       |        |       |  |
| 90.   | 65.    | 21.     | 11.     | 3064.        |      |       |        |       |  |
| CFS   | 17.67  | 22.52   | 23.30   | 23.30        |      |       |        |       |  |
| CMS   | 448.74 | 571.99  | 591.78  | 591.78       |      |       |        |       |  |
| INCHES  | 1130.  | 1441.   | 1490.   | 1490.        |      |       |        |       |  |
| MM  | 1394.  | 1777.   | 1838.   | 1838.        |      |       |        |       |  |
| AC-FT   |        |         |         |              |      |       |        |       |  |
| THOUS CU M  |        |         |         |              |      |       |        |       |  |

SUM OF LEBANON  
 DAM NO.1 INFLOW  
 HYDROGRAPH  
 AND LEBANON  
 DAM NO.2  
 OUTFLOW  
 HYDROGRAPH.



JECT DAM SAFETY INSPECTION  
LEBANON DAM NO. 1  
 BY DJS DATE 2-13-80 PROJ. NO. 79-203-595  
 CHKD. BY DLB DATE 2-14-80 SHEET NO. H OF V



Engineers • Geologists • Planners  
 Environmental Specialists

0.3 PMF

PEAK OUTFLOW IS 940. AT TIME 42.50 HOURS

|            | 6-HOUR | 24-HOUR | 72-HOUR | TOTAL VOLUME |
|------------|--------|---------|---------|--------------|
| PEAK       | 940.   | 212.    | 109.    | 31270.       |
| CFS        | 667.   | 3.      | 3.      | 806.         |
| INCHES     | 5.17   | 6.57    | 6.74    | 6.74         |
| MM         | 131.32 | 166.91  | 171.07  | 171.07       |
| AC-FT      | 331.   | 420.    | 431.    | 431.         |
| THOUS CU M | 408.   | 518.    | 531.    | 531.         |

0.5 PMF

PEAK OUTFLOW IS 1588. AT TIME 42.33 HOURS

|            | 6-HOUR | 24-HOUR | 72-HOUR | TOTAL VOLUME |
|------------|--------|---------|---------|--------------|
| PEAK       | 1588.  | 356.    | 163.    | 52752.       |
| CFS        | 1128.  | 10.     | 5.      | 1494.        |
| INCHES     | 8.74   | 11.05   | 11.36   | 11.36        |
| MM         | 222.07 | 280.59  | 288.52  | 288.52       |
| AC-FT      | 559.   | 707.    | 727.    | 727.         |
| THOUS CU M | 690.   | 872.    | 896.    | 896.         |

PMF

PEAK OUTFLOW IS 3173. AT TIME 42.17 HOURS

|            | 6-HOUR | 24-HOUR | 72-HOUR | TOTAL VOLUME |
|------------|--------|---------|---------|--------------|
| PEAK       | 3173.  | 719.    | 370.    | 106658.      |
| CFS        | 2274.  | 20.     | 10.     | 3020.        |
| INCHES     | 17.63  | 22.28   | 22.97   | 22.97        |
| MM         | 447.71 | 565.96  | 583.36  | 583.36       |
| AC-FT      | 1128.  | 1425.   | 1469.   | 1469.        |
| THOUS CU M | 1391.  | 1758.   | 1812.   | 1812.        |

#### HYDROGRAPH ROUTING

ROUTE FROM DAM NO. 1 TO SECTION 21 2700 FT U.S. OF DAM

| ISTAU | ICUMP | IECUM | IEAPE | JPL1  | JPRE  | ISAME | ISAGE  | IAUTU |
|-------|-------|-------|-------|-------|-------|-------|--------|-------|
| 102   | 1     | 0     | 0     | 0     | 0     | 1     | 0      | 0     |
| QLOSS | CLOSS | AVG   | INES  | ISAME | LUPT  | IPMP  | LSTR   |       |
| 0.0   | 0.000 | 0.00  | 1     | 1     | 0     | 0     | 0      |       |
| MSIPS | MSUL  | LAG   | AMSK  | A     | TSA   | STOKA | ISPRAT |       |
| 1     | 0     | 0     | 0.000 | 0.000 | 0.000 | -1.   | 0      |       |

#### NORMAL DEPTH CHANNEL ROUTING

UN(1) UN(2) UN(3) ELHVT ELMAX ELMTM REL  
 .0500 .0650 .0500 541.0 560.0 2700. .01500

LEBANON  
 DAM NO. 1  
 OUTFLOW  
 HYDROGRAPHS

## DAM SAFETY INSPECTION

LETANON DAM No. 1

BY DJS

DATE \_\_\_\_\_

2-12-80

**PROJ. NO.**

79-203 - 595

CHKD. BY DLB

DATE \_\_\_\_\_

2-14-80

**SHEET NO.**

I OF V



**Engineers • Geologists • Planners  
Environmental Specialists**

CROSS SECTION COORDINATES--STA. ELEV. STA. ELEV--ETC

|          | 0.00     | .37      | .67      | 7.22      | 25.18     | 52.00     | 80.15     | 131.24    | 192.07    |
|----------|----------|----------|----------|-----------|-----------|-----------|-----------|-----------|-----------|
| STONAGE  | 306.91   | 386.94   | 462.87   | 552.89    | 650.99    | 757.18    | 871.45    | 993.80    | 1124.24   |
| CUFTFLUM | 0.00     | 20.38    | 68.10    | 370.86    | 1635.83   | 4502.22   | 9051.62   | 15516.42  | 24125.85  |
|          | 48655.53 | 64994.22 | 84167.55 | 106563.66 | 123380.86 | 161812.18 | 195045.79 | 232265.39 | 273650.61 |
| STAGE    | 541.00   | 542.00   | 543.00   | 544.00    | 545.00    | 546.00    | 547.00    | 548.00    | 549.00    |
|          | 551.00   | 552.00   | 553.00   | 554.00    | 555.00    | 556.00    | 557.00    | 558.00    | 559.00    |
| FLUM     | 0.00     | 20.38    | 68.10    | 370.86    | 1635.83   | 4502.22   | 9051.62   | 15516.42  | 24125.85  |
|          | 48655.53 | 64994.22 | 84167.55 | 106563.66 | 123380.86 | 161812.18 | 195045.79 | 232265.39 | 273650.61 |

## HYDROGRAPH KNOTTING

ROUTE FROM SECTION 2 TO SECTION 3: 4550 FT O.S. UP DAM

| QLOSS | ISTAU | ICUMP | ICUN | IAVE         | JPL1  | JPRF  | INAME | ISTAGE | TAUTO |
|-------|-------|-------|------|--------------|-------|-------|-------|--------|-------|
| 0.0   | 203   | 1     | 0    | 0            | 0     | 0     | 1     | 0      | 0     |
|       |       |       |      | ROUTING DATA |       |       |       |        |       |
|       | CLOSS | AVG   | IRIS | ISAME        | IUPZ  | IPMP  |       | LSTR   |       |
|       | 0.000 | 0.00  | 1    | 1            | 0     | 0     |       |        |       |
|       | MSF5  | MSDCL | LAG  | AMSKK        | X     | TSK   | STUHA | ISPRAT |       |
|       | 1     | 0     | 0    | 0.000        | 0.000 | 0.000 | -1    | 0      |       |

### **NORMAL DEPTH CHANNEL ROUTING**

| UN(1) | UN(2) | UN(3) | ELMVT | ELMAX | HLNTH | SEL    |
|-------|-------|-------|-------|-------|-------|--------|
| .0550 | .0450 | .0550 | 527.0 | 560.0 | 1850. | .00900 |

## CROSS SECTION COORDINATES--STA. ELEV. STA. ELEV.--ETC

| CRUSS SECTION COORDINATES--STA., ELEV., STA. LEV.--ETC. |           |           |           |           |           |          |           |           |           |   |
|---|-----------|-----------|-----------|-----------|-----------|----------|-----------|-----------|-----------|---|
|   | 0.00      | 1.00      | 3.23      | 17.20     | 46.98     | 92.55    | 153.93    | 240.26    | 374.31    |   |
|   | 668.20    | 821.87    | 980.03    | 1142.67   | 1309.79   | 1481.40  | 1657.49   | 1838.07   | 2023.13   |   |
| STORAGE   | 0.00      | 1.00      | 3.23      | 17.20     | 46.98     | 92.55    | 153.93    | 240.26    | 374.31    |   |
|   | 0.00      | 200.00    | 540.00    | 1397.00   | 1400.00   | 527.00   | 1410.00   | 527.00    |           |   |
|   | 1450.00   | 538.00    | 2100.00   | 540.00    | 2600.00   | 560.00   |           |           |           |   |
| OUTFLOW   | 0.00      | 90.30     | 354.76    | 1590.96   | 5210.97   | 12393.62 | 23758.54  | 41029.10  | 70791.89  |   |
|   | 166268.13 | 227546.07 | 297307.48 | 375317.53 | 461422.45 | 55520.91 | 657548.55 | 767463.37 | 885254.20 | 1 |
| STAGE   | 527.00    | 520.74    | 530.47    | 532.21    | 533.95    | 535.88   | 537.42    | 539.16    | 540.89    |   |
|   | 504.37    | 506.11    | 507.84    | 509.58    | 511.32    | 513.05   | 514.79    | 516.53    | 518.26    |   |
| FLOW  | 0.00      | 90.30     | 354.76    | 1590.96   | 5210.97   | 12393.62 | 23758.54  | 41029.10  | 70791.89  |   |
|   | 166268.13 | 227546.07 | 297307.48 | 375317.53 | 461422.45 | 55520.91 | 657548.55 | 767463.37 | 885254.20 | 1 |

SUBJECT DAM SAFETY INSPECTION  
LEBANON DAM No. 1  
 BY DJS DATE 2-12-80 PROJ. NO. 79-203-S95  
 CHKD. BY DLB DATE 2-14-80 SHEET NO. J OF V



Engineers • Geologists • Planners  
 Environmental Specialists

\*\*\*\*\*

HYDROGRAPH ROUTING

ROUTE FROM SECTION 3 TO SECTION 47 6050 FT D.S. OF DAM

| ISTAU        | ICOMP | IECON | ITAPE | JPL1  | JPH1  | INAME | ISTAGE | IAUTU |
|--------------|-------|-------|-------|-------|-------|-------|--------|-------|
| 304          | 1     | 0     | 0     | 0     | 0     | 1     | 0      | 0     |
| ROUTING DATA |       |       |       |       |       |       |        |       |
| QLOSS        | CLASS | AVG   | IRES  | ISAME | IOPT  | IPMP  | LSTM   |       |
| 0.0          | 0.000 | 0.00  | 1     | 1     | 0     | 0     | 0      |       |
| ROUTING DATA |       |       |       |       |       |       |        |       |
| MSIPS        | MSIDL | LAG   | ANSK  | A     | TSK   | STURA | ISPRAT |       |
| 1            | 0     | 0     | 0.000 | 0.000 | 0.000 | -1.   | 0      |       |

\*\*\*\*\*

BURNAL DEPTH CHANNEL ROUTING

UN(1) UN(2) UN(3) ELMAX ELMTW SEL  
 .0550 .0450 516.0 540.0 1500. .00500

CROSS SECTION COORDINATES--STA.ELEV.STA.ELEV--ETC  
 0.00 540.00 200.00 524.00 977.00 519.00 980.00 516.00 990.00 516.00  
 993.00 519.00 1200.00 523.00 2150.00 540.00

|         |          |          |          |           |           |           |           |           |           |
|---------|----------|----------|----------|-----------|-----------|-----------|-----------|-----------|-----------|
| STORAGE | 0.00     | .49      | 1.09     | 4.00      | 17.50     | 42.38     | 78.67     | 124.79    | 175.10    |
|         | 206.99   | 348.58   | 413.92   | 483.01    | 555.87    | 632.48    | 712.85    | 796.97    | 884.86    |
| OUTFLOW | 0.00     | 34.37    | 111.48   | 306.30    | 1266.32   | 3684.05   | 8092.74   | 15649.05  | 26095.54  |
|         | 54469.12 | 72424.89 | 92942.85 | 116072.54 | 141869.27 | 170392.27 | 201703.44 | 235866.58 | 272946.75 |
| STAGE   | 516.00   | 517.26   | 518.53   | 519.79    | 521.05    | 522.32    | 523.58    | 524.84    | 526.11    |
|         | 528.63   | 529.89   | 531.16   | 532.42    | 533.68    | 534.95    | 536.21    | 537.47    | 538.74    |
| FLOW    | 0.00     | 34.37    | 111.48   | 306.30    | 1266.32   | 3684.05   | 8092.74   | 15649.05  | 26095.54  |
|         | 54469.12 | 72424.89 | 92942.85 | 116072.54 | 141869.27 | 170392.27 | 201703.44 | 235866.58 | 272946.75 |

\*\*\*\*\*

HYDROGRAPH ROUTING

ROUTE FROM SECTION 4 TO SECTION 51 6650 FT D.S. OF DAM

| ISTAU        | ICOMP | IECON | ITAPE | JPL1  | JPH1  | INAME | ISTAGE | IAUTU |
|--------------|-------|-------|-------|-------|-------|-------|--------|-------|
| 405          | 0     | 0     | 0     | 0     | 0     | 1     | 0      | 0     |
| ROUTING DATA |       |       |       |       |       |       |        |       |
| QLOSS        | CLASS | AVG   | IRES  | ISAME | IOPT  | IPMP  | LSTM   |       |
| 0.0          | 0.000 | 0.00  | 1     | 1     | 0     | 0     | 0      |       |
| ROUTING DATA |       |       |       |       |       |       |        |       |
| MSIPS        | MSIDL | LAG   | ANSK  | A     | TSK   | STURA | ISPRAT |       |
| 1            | 0     | 0     | 0.000 | 0.000 | 0.000 | -1.   | 0      |       |

\*\*\*\*\*



SUBJECT DAM SAFETY INSPECTION  
LEBANON DAM No. 1  
 BY DJS DATE 2-12-80 PROJ. NO. 79-203-SYS  
 CHKD. BY DLB DATE 2-14-80 SHEET NO. 1 OF V



SUMMARY OF DAM SAFETY ANALYSIS

LEBANON DAM

NO. 2; OVERTOPPING

OCCURS AT

APPROXIMATELY

0.21 PMF.

| RATIO<br>OF<br>PMF | MAXIMUM<br>RESERVOIR<br>W.S. ELEV | MAXIMUM<br>DEPTH<br>OVER DAM | MAXIMUM<br>STORAGE<br>AC-FT | MAXIMUM<br>OUTFLOW<br>CFS | DURATION<br>OVER TOP<br>HOURS | TIME OF<br>MAX OUTFLOW<br>HOURS | TIME OF<br>FAILURE<br>HOURS |
|--------------------|-----------------------------------|------------------------------|-----------------------------|---------------------------|-------------------------------|---------------------------------|-----------------------------|
| .10                | 678.19                            | 0.00                         | 170.                        | 151.                      | 0.00                          | 42.67                           | 0.00                        |
| .20                | 679.61                            | 0.00                         | 184.                        | 317.                      | 0.00                          | 42.67                           | 0.00                        |
| .31*               | 679.80                            | —                            | 186.                        | 340.                      | —                             | —                               | —                           |
| .30                | 680.08                            | .28                          | 189.                        | 533.                      | 2.50                          | 41.83                           | 0.00                        |
| .50                | 680.30                            | .50                          | 191.                        | 889.                      | 4.50                          | 41.83                           | 0.00                        |
| 1.00               | 680.68                            | .88                          | 195.                        | 1780.                     | 6.50                          | 41.83                           | 0.00                        |

\* INTERPOLATED VALUES; OVERTOPPING OCCURS @ APPROXIMATELY 0.21 PMF.

LEBANON DAM

NO. 1; OVERTOPPING

OCCURS AT

APPROXIMATELY

0.16 PMF.

| RATIO<br>OF<br>PMF | MAXIMUM<br>RESERVOIR<br>W.S. ELEV | MAXIMUM<br>DEPTH<br>OVER DAM | MAXIMUM<br>STORAGE<br>AC-FT | MAXIMUM<br>OUTFLOW<br>CFS | DURATION<br>OVER TOP<br>HOURS | TIME OF<br>MAX OUTFLOW<br>HOURS | TIME OF<br>FAILURE<br>HOURS |
|--------------------|-----------------------------------|------------------------------|-----------------------------|---------------------------|-------------------------------|---------------------------------|-----------------------------|
| .10                | 624.58                            | 0.00                         | 75.                         | 289.                      | 0.00                          | 43.17                           | 0.00                        |
| .16**              | 625.30                            | —                            | 82.                         | 470.                      | —                             | —                               | —                           |
| .20                | 625.61                            | .31                          | 86.                         | 603.                      | 2.67                          | 43.00                           | 0.00                        |
| .30                | 626.25                            | .95                          | 93.                         | 948.                      | 4.50                          | 42.50                           | 0.00                        |
| .50                | 627.06                            | 1.76                         | 103.                        | 1548.                     | 6.33                          | 42.33                           | 0.00                        |
| 1.00               | 627.79                            | 2.49                         | 112.                        | 3173.                     | 8.50                          | 42.17                           | 0.00                        |

\*\* INTERPOLATED VALUES; OVERTOPPING OCCURS @ APPROXIMATELY 0.16 PMF.

SUBJECT DAM SAFETY INSPECTION  
LEBANON DAM NO. 1  
 BY DJS DATE 2-12-80 PROJ. NO. 79-203-595  
 CHKD. BY DLB DATE 2-14-80 SHEET NO. M OF V



SECTION 2, APPROXIMATELY  
 2700 FT DOWNSTREAM FROM  
 LEBANON DAM NO. 1

SECTION 3, APPROXIMATELY  
 4550 FT D.S. FROM LEBANON  
 DAM NO. 1

SECTION 4, APPROXIMATELY  
 6050 FT D.S. FROM LEBANON  
 DAM NO. 1

SECTION 5, APPROXIMATELY  
 8650 FT D.S. FROM LEBANON  
 DAM NO. 1

SECTION 6, APPROXIMATELY  
 13,550 FT D.S. FROM LEBANON  
 DAM NO. 1

PLAN 1 STATION 102

| RATIO | MAXIMUM<br>FLOW, CFS | MAXIMUM<br>STAGE, FT | TIME<br>HOURS |
|-------|----------------------|----------------------|---------------|
| .10   | 287.                 | 543.7                | 43.50         |
| .20   | 600.                 | 544.2                | 43.17         |
| .30   | 943.                 | 544.5                | 42.67         |
| .50   | 1582.                | 545.0                | 42.50         |
| 1.00  | 3169.                | 545.5                | 42.33         |

PLAN 1 STATION 203

| RATIO | MAXIMUM<br>FLOW, CFS | MAXIMUM<br>STAGE, FT | TIME<br>HOURS |
|-------|----------------------|----------------------|---------------|
| .10   | 286.                 | 530.0                | 43.67         |
| .20   | 599.                 | 530.8                | 43.33         |
| .30   | 940.                 | 531.3                | 42.67         |
| .50   | 1577.                | 532.2                | 42.67         |
| 1.00  | 3163.                | 533.0                | 42.50         |

PLAN 1 STATION 304

| RATIO | MAXIMUM<br>FLOW, CFS | MAXIMUM<br>STAGE, FT | TIME<br>HOURS |
|-------|----------------------|----------------------|---------------|
| .10   | 285.                 | 519.7                | 43.83         |
| .20   | 596.                 | 520.2                | 43.50         |
| .30   | 935.                 | 520.6                | 43.00         |
| .50   | 1573.                | 521.2                | 42.67         |
| 1.00  | 3157.                | 522.0                | 42.50         |

PLAN 1 STATION 405

| RATIO | MAXIMUM<br>FLOW, CFS | MAXIMUM<br>STAGE, FT | TIME<br>HOURS |
|-------|----------------------|----------------------|---------------|
| .10   | 284.                 | 502.5                | 44.00         |
| .20   | 594.                 | 503.7                | 43.67         |
| .30   | 930.                 | 504.3                | 43.17         |
| .50   | 1566.                | 505.4                | 42.83         |
| 1.00  | 3151.                | 506.7                | 42.67         |

PLAN 1 STATION 506

| RATIO | MAXIMUM<br>FLOW, CFS | MAXIMUM<br>STAGE, FT | TIME<br>HOURS |
|-------|----------------------|----------------------|---------------|
| .10   | 274.                 | 475.6                | 44.50         |
| .20   | 576.                 | 476.6                | 44.17         |
| .30   | 894.                 | 477.1                | 43.67         |
| .50   | 1522.                | 477.9                | 43.33         |
| 1.00  | 3095.                | 479.0                | 43.00         |



PROJECT DAM SAFETY INSPECTION  
LEBANON DAM NO. 1  
 BY DJS DATE 2-12-80 PROJ. NO. 79-203-595  
 CHKD. BY DLB DATE 2-14-80 SHEET NO. N OF V



# BREACHING ANALYSIS

DAM SAFETY INSPECTION  
 LEBANON DAM #1 W/O.S. LEBANON DAM #2 \*\*\*\* BREACHING ANALYSIS \*\*\*\*  
 10-MINUTE TIME STEP AND 48-HOUR STORM DURATION

LEBANON  
 DAM NO. 2

(SAME INPUT  
 DATA AS FOR  
 OVERTOPPING  
 ANALYSIS, WITH  
 THE ADDITION  
 OF BREACH  
 CONDITIONS  
 GIVEN HERE)

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

## HYDROGRAPH ROUTING

ROUTE THROUGH RESERVOIR - LEBANON DAM NO. 2

| DAM DATA |      |      |        |
|----------|------|------|--------|
| TUPEL    | CUND | EXPU | DAMWID |
| 679.8    | 0.0  | 0.0  | 0.     |

| DAM BREACH DATA |     |        |        |
|-----------------|-----|--------|--------|
| BRWID           | Z   | ELBM   | TFAIL  |
| 0.              | .50 | 640.00 | .50    |
|                 |     |        | WSEL   |
|                 |     |        | 676.00 |
|                 |     |        | 679.80 |

STATION AM #2 . PLAN 1. RATIO 1

BEGIN DAM FAILURE AT 41.83 HOURS

PEAK OUTFLOW IS 5007. AT TIME 42.33 HOURS

①

| DAM BREACH DATA |     |        |        |
|-----------------|-----|--------|--------|
| BRWID           | Z   | ELBM   | TFAIL  |
| 300.            | .50 | 640.00 | .50    |
|                 |     |        | WSEL   |
|                 |     |        | 676.00 |
|                 |     |        | 679.80 |

STATION AM #2 . PLAN 2. RATIO 1

BEGIN DAM FAILURE AT 41.83 HOURS

PEAK OUTFLOW IS 8125. AT TIME 42.00 HOURS

②

| DAM BREACH DATA |     |        |        |
|-----------------|-----|--------|--------|
| BRWID           | Z   | ELBM   | TFAIL  |
| 0.              | .50 | 640.00 | 4.00   |
|                 |     |        | WSEL   |
|                 |     |        | 676.00 |
|                 |     |        | 679.80 |

STATION AM #2 . PLAN 3. RATIO 1

BEGIN DAM FAILURE AT 41.83 HOURS

PEAK OUTFLOW IS 1074. AT TIME 44.33 HOURS

③

ECT \_\_\_\_\_ DAM SAFETY INSPECTION \_\_\_\_\_  
LEBANON DAM No. 1  
 BY DJS DATE 2-12-80 PROJ. NO. 79-203-595  
 CHKD. BY DLB DATE 2-14-80 SHEET NO. 0 OF 1



PLAN

④

DAM BREACH DATA  
 2 ELBM TFAIL WSEL FAILED  
 5.00 640.00 4.00 676.00 679.00  
 STATION AN #2 . PLAN 4. RATIO 1

BEGIN DAM FAILURE AT 41.83 HOURS

PEAK OUTFLOW IS 1512. AT TIME 42.17 HOURS

DAM BREACH DATA  
 2 ELBM TFAIL WSEL FAILED  
 1.00 640.00 2.00 676.00 679.00  
 STATION AN #2 . PLAN 5. RATIO 1

BEGIN DAM FAILURE AT 41.83 HOURS

PEAK OUTFLOW IS 2336. AT TIME 42.29 HOURS

⑤

AD-A085 227

GAI CONSULTANTS INC MONROEVILLE PA  
NATIONAL DAM INSPECTION REPORT. LEBANON RESERVOIR DAM NUMBER 1.---ETC(U)  
MAR 80 B M MIHALCIN

F/6 13/13

DACW311-80-C-0016

NL


UNCLASSIFIED

2 of 2

ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED



END  
DATE  
FILMED  
6-80  
DTIC



MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

ECT

## DAM SAFETY INSPECTION

LEBANON DAM No. 1

BY DJS

DATE

2-12-80

PROJ. NO.

79-203-S9SCHKD. BY DLB

DATE

2-14-80

SHEET NO.

P OF V

CONSULTANTS, INC.

Engineers • Geologists • Planners  
Environmental Specialists

THE DAM BREACH HYDROGRAPH WAS DEVELOPED USING A TIME INTERVAL OF .010 HOURS DURING BREACH FORMATION. DUNSTAN CALCULATIONS WILL USE A TIME INTERVAL OF .167 HOURS. THIS TABLE COMPARES THE HYDROGRAPH FOR DUNSTAN CALCULATIONS WITH THE COMPUTED BREACH HYDROGRAPH. INTERMEDIATE PLUMS ARE INTERPOLATED FROM END-OF-PERIOD VALUES.

| TIME<br>(HOURS) | TIME FROM<br>BEGINNING<br>OF BREACH<br>(HOURS) | INTERPOLATED<br>BREACH<br>HYDROGRAPH<br>(CFS) | COMPUTED<br>BREACH<br>HYDROGRAPH<br>(CFS) | ΔBROM<br>ERROR<br>(CFS) | ACCUMULATED<br>ERROR<br>(CFS) | ACCUMULATED<br>ERROR<br>(AC-FT) |
|-----------------|--|---|---|-------------------------|-------------------------------|---------------------------------|
| 41.833          | 0.000  | 377.  | 377.                                      | 0.                      | 0.                            | 0.                              |
| 41.843          | .010   | 833.  | 1036.                                     | -203.                   | -203.                         | -0.                             |
| 41.853          | .020   | 1289.   | 2063.                                     | -775.                   | -978.                         | -1.                             |
| 41.863          | .029   | 1744.   | 3203.                                     | -1459.                  | -2436.                        | -2.                             |
| 41.873          | .039   | 2200.   | 4311.                                     | -2111.                  | -4548.                        | -4.                             |
| 41.882          | .049   | 2656.   | 5319.                                     | -2663.                  | -7211.                        | -6.                             |
| 41.892          | .059   | 3112.   | 6198.                                     | -3086.                  | -10297.                       | -8.                             |
| 41.902          | .069   | 3567.   | 6936.                                     | -3369.                  | -13665.                       | -11.                            |
| 41.912          | .078   | 4023.   | 7394.                                     | -3371.                  | -17037.                       | -14.                            |
| 41.922          | .088   | 4479.   | 7757.                                     | -3278.                  | -20315.                       | -16.                            |
| 41.931          | .098   | 4935.   | 8049.                                     | -3114.                  | -23429.                       | -19.                            |
| 41.941          | .108   | 5391.   | 8095.                                     | -2704.                  | -26133.                       | -21.                            |
| 41.951          | .118   | 5846.   | 8104.                                     | -2258.                  | -28391.                       | -23.                            |
| 41.961          | .127   | 6302.   | 8111.                                     | -1809.                  | -30201.                       | -24.                            |
| 41.971          | .137   | 6758.   | 8117.                                     | -1359.                  | -31559.                       | -26.                            |
| 41.980          | .147   | 7214.   | 8120.                                     | -907.                   | -32466.                       | -26.                            |
| 41.990          | .157   | 7669.   | 8123.                                     | -454.                   | -32920.                       | -27.                            |
| 42.000          | .167   | 8125.   | 8125.                                     | 0.                      | -32920.                       | -27.                            |
| 42.010          | .176   | 7907.   | 8053.                                     | -146.                   | -33066.                       | -27.                            |
| 42.020          | .186   | 7689.   | 7655.                                     | 35.                     | -33332.                       | -27.                            |
| 42.029          | .196   | 7471.   | 7385.                                     | 87.                     | -33645.                       | -27.                            |
| 42.039          | .206   | 7254.   | 7200.                                     | 54.                     | -33991.                       | -27.                            |
| 42.049          | .216   | 7036.   | 7072.                                     | 37.                     | -34328.                       | -27.                            |
| 42.059          | .225   | 6818.   | 6884.                                     | -66.                    | -34694.                       | -27.                            |
| 42.069          | .235   | 6600.   | 6606.                                     | -6.                     | -35000.                       | -27.                            |
| 42.078          | .245   | 6382.   | 6391.                                     | -9.                     | -35309.                       | -27.                            |
| 42.088          | .255   | 6164.   | 6126.                                     | 38.                     | -35617.                       | -27.                            |
| 42.098          | .265   | 5946.   | 5954.                                     | -8.                     | -35925.                       | -27.                            |
| 42.108          | .275   | 5728.   | 5842.                                     | -113.                   | -36239.                       | -27.                            |
| 42.118          | .284   | 5511.   | 5768.                                     | -257.                   | -36549.                       | -27.                            |
| 42.127          | .294   | 5293.   | 5472.                                     | -180.                   | -36859.                       | -27.                            |
| 42.137          | .304   | 5075.   | 4972.                                     | 103.                    | -37166.                       | -27.                            |
| 42.147          | .314   | 4857.   | 4687.                                     | 170.                    | -37473.                       | -27.                            |
| 42.157          | .324   | 4639.   | 4520.                                     | 119.                    | -37780.                       | -27.                            |
| 42.167          | .333   | 4421.   | 4421.                                     | 0.                      | -38087.                       | -27.                            |
| 42.176          | .343   | 4197.   | 4362.                                     | -165.                   | -38394.                       | -27.                            |
| 42.186          | .353   | 3973.   | 3900.                                     | 74.                     | -38701.                       | -27.                            |
| 42.196          | .363   | 3749.   | 3508.                                     | 241.                    | -39008.                       | -27.                            |
| 42.206          | .373   | 3525.   | 3316.                                     | 209.                    | -39315.                       | -27.                            |
| 42.216          | .382   | 3301.   | 3218.                                     | 83.                     | -39622.                       | -27.                            |
| 42.225          | .392   | 3077.   | 3168.                                     | -51.                    | -39929.                       | -27.                            |
| 42.235          | .402   | 2853.   | 3101.                                     | -208.                   | -40236.                       | -27.                            |
| 42.245          | .412   | 2629.   | 2149.                                     | 480.                    | -40543.                       | -27.                            |
| 42.255          | .422   | 2405.   | 1800.                                     | 525.                    | -40850.                       | -27.                            |
| 42.265          | .431   | 2181.   | 1799.                                     | 2.                      | -41157.                       | -27.                            |
| 42.275          | .441   | 1957.   | 1774.                                     | 183.                    | -41464.                       | -27.                            |
| 42.284          | .451   | 1733.   | 1765.                                     | -32.                    | -41771.                       | -27.                            |
| 42.294          | .461   | 1509.   | 945.                                      | 564.                    | -42078.                       | -27.                            |
| 42.304          | .471   | 1285.   | 454.                                      | 831.                    | -42385.                       | -27.                            |
| 42.314          | .480   | 1061.   | 665.                                      | 396.                    | -42692.                       | -27.                            |
| 42.324          | .490   | 837.  | 576.                                      | 261.                    | -42999.                       | -27.                            |
| 42.333          | .500   | 613.  | 613.                                      | 0.                      | -43306.                       | -27.                            |

PLAN

②

SUBJECT

DAM SAFETY INSPECTION

LEONARD DAM No. 1

BY DJS

DATE

2-12-80

PROJ. NO.

7A-203-595

CHKD. BY DLB

DATE

2-14-80

SHEET NO.

Q

OF

V



CONSULTANTS, INC.

Engineers • Geologists • Planners  
Environmental Specialists

(1) POINTS AT MINUTAL TIME INTERVAL

(2) INTERPOLATED BREACH HYDROGRAPH  
(3) COMPUTED BREACH HYDROGRAPH

TIME  
(HRS)

41.03 1.  
41.04 2.  
41.05 3.  
41.06 4.  
41.07 5.  
41.08 6.  
41.09 7.  
41.10 8.  
41.11 9.  
41.12 10.  
41.13 11.  
41.14 12.  
41.15 13.  
41.16 14.  
41.17 15.  
41.18 16.  
41.19 17.  
41.20 18.  
41.21 19.  
41.22 20.  
41.23 21.  
41.24 22.  
41.25 23.  
41.26 24.  
41.27 25.  
41.28 26.  
41.29 27.  
41.30 28.  
41.31 29.  
41.32 30.  
41.33 31.  
41.34 32.  
41.35 33.  
41.36 34.  
41.37 35.  
41.38 36.  
41.39 37.  
41.40 38.  
41.41 39.  
41.42 40.  
41.43 41.  
41.44 42.  
41.45 43.  
41.46 44.  
41.47 45.  
41.48 46.  
41.49 47.  
41.50 48.  
41.51 49.  
41.52 50.

PLAN

(2)

JECT

DAM SAFETY INSPECTION

LEBANON DAM No. 1

BY DJS DATE 2-13-80 PROJ. NO. 79-203-595

CHKD. BY DLD DATE 2-14-80 SHEET NO. B OF V



Engineers • Geologists • Planners  
Environmental Specialists

LEBANON  
DAM NO. 1

PLAN

HYDROGRAPH ROUTING

ROUTE TOTAL HYDROGRAPH THROUGH RESERVOIR #1

DAM BREACH DATA  
BRID 2 ELUM TFAIL WSEL FAILED  
0. 1.00 603.00 .50 622.50 625.30

STATION AN = 1 . PLAN 1, RATIO 1

BEGIN DAM FAILURE AT 41.33 HOURS

PEAK OUTFLOW IS 433. AT TIME 42.50 HOURS

DAM BREACH DATA  
BRID 2 ELUM TFAIL WSEL FAILED  
300. 0.00 603.00 .50 622.50 625.30

STATION AN = 1 . PLAN 2, RATIO 1

BEGIN DAM FAILURE AT 41.33 HOURS

PEAK OUTFLOW IS 8375. AT TIME 42.00 HOURS

DAM BREACH DATA  
BRID 2 ELUM TFAIL WSEL FAILED  
0. 1.00 603.00 4.00 622.50 625.30

STATION AN = 1 . PLAN 3, RATIO 1

BEGIN DAM FAILURE AT 41.33 HOURS

PEAK OUTFLOW IS 1809. AT TIME 44.50 HOURS

DAM BREACH DATA  
BRID 2 ELUM TFAIL WSEL FAILED  
300. 0.00 603.00 4.00 622.50 625.30

STATION AN = 1 . PLAN 4, RATIO 1

BEGIN DAM FAILURE AT 41.33 HOURS

PEAK OUTFLOW IS 2390. AT TIME 42.25 HOURS

DAM BREACH DATA  
BRID 2 ELUM TFAIL WSEL FAILED  
75. 2.00 603.00 2.00 622.50 625.30

STATION AN = 1 . PLAN 5, RATIO 1

BEGIN DAM FAILURE AT 41.33 HOURS

PEAK OUTFLOW IS 3510. AT TIME 42.33 HOURS

①

②

③

④

⑤

PROJECT DAM SAFETY INSPECTION  
(LEWIS DAM No. 1)  
 BY DJS DATE 2-12-80 PROJ. NO. 79-203-595  
 CHKD. BY DLB DATE 2-14-80 SHEET NO. 5 OF V



THE DAM BREACH HYDROGRAPH WAS DEVELOPED USING A TIME INTERVAL OF .010 HOURS DURING BREACH FORMATION. DUNSTAN CALCULATIONS WILL USE A TIME INTERVAL OF .167 HOURS. THIS TABLE COMPARES THE HYDROGRAPH FOR DUNSTAN CALCULATIONS WITH THE COMPUTED BREACH HYDROGRAPH. INTERMEDIATE FLOWS ARE INTERPOLATED FROM END-OF-PERIOD VALUES.

| TIME (HOURS) | TIME BEGINNING OF BREACH (HOURS) | TIME FROM INTERPOLATED BREACH HYDROGRAPH (CFS) | COMPUTED BREACH HYDROGRAPH (CFS) | ERRNUN (CFS) | ACCUMULATED ERRNUN (CFS) | ACCUMULATED ERRNUN (AC-FT) |
|--------------|----------------------------------|--|----------------------------------|--------------|--------------------------|----------------------------|
| 41.333       | 0.000                            | 496.   | 496.                             | 0.           | 0.                       | 0.                         |
| 41.343       | .010                             | 791.   | 791.                             | -42.         | -42.                     | -0.                        |
| 41.353       | .020                             | 1003.  | 1249.                            | -246.        | -287.                    | -0.                        |
| 41.363       | .029                             | 1257.  | 1776.                            | -519.        | -807.                    | -1.                        |
| 41.373       | .039                             | 1511.  | 2314.                            | -804.        | -1610.                   | -1.                        |
| 41.382       | .049                             | 1764.  | 2828.                            | -1064.       | -2674.                   | -2.                        |
| 41.392       | .059                             | 2018.  | 3300.                            | -1281.       | -3956.                   | -3.                        |
| 41.402       | .069                             | 2272.  | 3711.                            | -1439.       | -5394.                   | -4.                        |
| 41.412       | .078                             | 2526.  | 4054.                            | -1529.       | -6923.                   | -6.                        |
| 41.422       | .088                             | 2780.  | 4329.                            | -1550.       | -8473.                   | -7.                        |
| 41.431       | .098                             | 3033.  | 4566.                            | -1532.       | -10005.                  | -9.                        |
| 41.441       | .108                             | 3287.  | 4735.                            | -1488.       | -11453.                  | -9.                        |
| 41.451       | .118                             | 3561.  | 4847.                            | -1306.       | -12759.                  | -10.                       |
| 41.461       | .127                             | 3795.  | 4939.                            | -1145.       | -13904.                  | -11.                       |
| 41.471       | .137                             | 4048.  | 5012.                            | -932.        | -14835.                  | -12.                       |
| 41.480       | .147                             | 4302.  | 4967.                            | -665.        | -15501.                  | -13.                       |
| 41.490       | .157                             | 4556.  | 4908.                            | -352.        | -15853.                  | -13.                       |
| 41.500       | .167                             | 4810.  | 4810.                            | -0.          | -15853.                  | -13.                       |
| 41.510       | .176                             | 4631.  | 4679.                            | -48.         | -15901.                  | -13.                       |
| 41.520       | .186                             | 4453.  | 4524.                            | -71.         | -15971.                  | -13.                       |
| 41.529       | .196                             | 4275.  | 4348.                            | -74.         | -16045.                  | -13.                       |
| 41.539       | .206                             | 4096.  | 4159.                            | -63.         | -16108.                  | -13.                       |
| 41.549       | .216                             | 3918.  | 3960.                            | -42.         | -16150.                  | -13.                       |
| 41.559       | .225                             | 3739.  | 3756.                            | -17.         | -16167.                  | -13.                       |
| 41.569       | .235                             | 3561.  | 3550.                            | 11.          | -16155.                  | -13.                       |
| 41.578       | .245                             | 3383.  | 3344.                            | 39.          | -16117.                  | -13.                       |
| 41.588       | .255                             | 3204.  | 3141.                            | 63.          | -16054.                  | -13.                       |
| 41.598       | .265                             | 3026.  | 2943.                            | 82.          | -15971.                  | -13.                       |
| 41.608       | .275                             | 2847.  | 2752.                            | 96.          | -15876.                  | -13.                       |
| 41.618       | .284                             | 2669.  | 2568.                            | 101.         | -15774.                  | -13.                       |
| 41.627       | .294                             | 2491.  | 2391.                            | 99.          | -15675.                  | -13.                       |
| 41.637       | .304                             | 2312.  | 2224.                            | 88.          | -15567.                  | -13.                       |
| 41.647       | .314                             | 2134.  | 2066.                            | 68.          | -15440.                  | -13.                       |
| 41.657       | .324                             | 1955.  | 1917.                            | 39.          | -15400.                  | -13.                       |
| 41.667       | .333                             | 1777.  | 1777.                            | 0.           | -15400.                  | -13.                       |
| 41.676       | .343                             | 1714.  | 1647.                            | 67.          | -15413.                  | -12.                       |
| 41.686       | .353                             | 1651.  | 1528.                            | 124.         | -15289.                  | -12.                       |
| 41.696       | .363                             | 1588.  | 1417.                            | 171.         | -15118.                  | -12.                       |
| 41.706       | .373                             | 1526.  | 1316.                            | 209.         | -14909.                  | -12.                       |
| 41.716       | .382                             | 1463.  | 1224.                            | 234.         | -14671.                  | -12.                       |
| 41.725       | .392                             | 1400.  | 1141.                            | 259.         | -14412.                  | -12.                       |
| 41.735       | .402                             | 1337.  | 1066.                            | 271.         | -14141.                  | -12.                       |
| 41.745       | .412                             | 1274.  | 999.                             | 275.         | -13865.                  | -11.                       |
| 41.755       | .422                             | 1211.  | 940.                             | 272.         | -13594.                  | -11.                       |
| 41.765       | .431                             | 1148.  | 888.                             | 261.         | -13331.                  | -11.                       |
| 41.775       | .441                             | 1085.  | 843.                             | 242.         | -13091.                  | -11.                       |
| 41.784       | .451                             | 1023.  | 805.                             | 217.         | -12874.                  | -10.                       |
| 41.794       | .461                             | 960.   | 774.                             | 185.         | -12689.                  | -10.                       |
| 41.804       | .471                             | 897.   | 745.                             | 148.         | -12541.                  | -10.                       |
| 41.814       | .480                             | 834.   | 716.                             | 104.         | -12437.                  | -10.                       |
| 41.824       | .490                             | 771.   | 716.                             | 55.          | -12382.                  | -10.                       |
| 41.833       | .500                             | 708.   | 708.                             | 0.           | -12382.                  | -10.                       |

PLAN

(2)

DUE TO BREACHING OF DAM (3812) NO. 1 ONLY 4908.



JECT

DAM SAFETY INSPECTION

LEBANON DAM No. 1

BY DJS

DATE 2-12-80

PROJ. NO. 79-203-593

CHKD. BY DLB


DATE 2-14-80

SHEET NO. T OF V



CONSULTANTS, INC.

Engineers • Geologists • Planners  
Environmental Specialists



PROJECT DAM SAFETY INSPECTION  
LEBANON DAM No. 1  
 BY DJS DATE 2-12-80 PROJ. NO. 79-203-593  
 CHKD. BY DJA DATE 2-14-80 SHEET NO. U OF V



SUMMARY  
OUTPUT:

LEBANON  
DAM NO.2

LEBANON  
DAM NO.1

| RATIO<br>UP<br>PMF | ELEVATION<br>RESERVOIR<br>W.S.ELEV | INITIAL VALUE                |                             | SPILLWAY CHEST            |                               | TOP OF DAM           |                      | TIME OF<br>FAILURE<br>HOURS |
|--------------------|------------------------------------|------------------------------|-----------------------------|---------------------------|-------------------------------|----------------------|----------------------|-----------------------------|
|                    |                                    | MAXIMUM<br>DEPTH<br>OVER DAM | MAXIMUM<br>STORAGE<br>AC-FT | MAXIMUM<br>OUTFLOW<br>CFS | DURATION<br>OVER TOP<br>HOURS | MAX OUTFLOW<br>HOURS | MAX OUTFLOW<br>HOURS |                             |
| .24                | 679.87                             | .07                          | 187.                        | 5887.                     | .28                           | 42.33                | 41.83                | 41.83                       |
| .24                | 679.85                             | .05                          | 187.                        | 8125.                     | .18                           | 42.00                | 41.83                | 41.83                       |
| .24                | 679.93                             | .13                          | 187.                        | 1076.                     | .03                           | 44.33                | 41.83                | 41.83                       |
| .24                | 679.85                             | .05                          | 187.                        | 1512.                     | .17                           | 42.17                | 41.83                | 41.83                       |
| .24                | 679.86                             | .06                          | 187.                        | 2338.                     | .21                           | 42.29                | 41.83                | 41.83                       |

PLAN

① ② ③ ④ ⑤

| RATIO<br>UP<br>PMF | ELEVATION<br>RESERVOIR<br>W.S.ELEV | INITIAL VALUE                |                             | SPILLWAY CHEST            |                               | TOP OF DAM           |                      | TIME OF<br>FAILURE<br>HOURS |
|--------------------|------------------------------------|------------------------------|-----------------------------|---------------------------|-------------------------------|----------------------|----------------------|-----------------------------|
|                    |                                    | MAXIMUM<br>DEPTH<br>OVER DAM | MAXIMUM<br>STORAGE<br>AC-FT | MAXIMUM<br>OUTFLOW<br>CFS | DURATION<br>OVER TOP<br>HOURS | MAX OUTFLOW<br>HOURS | MAX OUTFLOW<br>HOURS |                             |
| .24                | 625.39                             | .09                          | 83.                         | 4333.                     | .34                           | 42.50                | 41.33                | 41.33                       |
| .24                | 625.34                             | .04                          | 83.                         | 8375.                     | .19                           | 42.00                | 41.33                | 41.33                       |
| .24                | 625.67                             | .37                          | 86.                         | 1809.                     | 1.83                          | 44.50                | 41.33                | 41.33                       |
| .24                | 625.34                             | .04                          | 83.                         | 2399.                     | .25                           | 42.25                | 41.33                | 41.33                       |
| .24                | 625.36                             | .06                          | 83.                         | 3518.                     | .25                           | 42.33                | 41.33                | 41.33                       |

① ② ③ ④ ⑤

| RATIO | STATION 102         |                     | TIME<br>HOURS |
|-------|---------------------|---------------------|---------------|
|       | MAXIMUM<br>FLUM,CFS | MAXIMUM<br>STAGE,FT |               |
| .24   | 3979.               | 545.8               | 42.50         |
| .24   | 6417.               | 546.4               | 42.17         |
| .24   | 1793.               | 545.1               | 44.67         |
| .24   | 2294.               | 545.2               | 42.23         |
| .24   | 3427.               | 545.6               | 42.50         |

SECTION 2

① ② ③ ④ ⑤

PROJECT DAM SAFETY INSPECTION  
LEDANON DAM No. 1  
 BY DTT DATE 2-12-80 PROJ. NO. 79-203-595  
 CHKD. BY DLB DATE 2-14-80 SHEET NO. V OF V



Engineers • Geologists • Planners  
 Environmental Specialists

### SECTION 3

| STATION | MAXIMUM<br>FLOW, CFS | MAXIMUM<br>STAGE, FT | TIME<br>HOURS |
|---------|----------------------|----------------------|---------------|
| 203     |                      |                      |               |
|         | 3824.                | 533.3                | 42.67         |
|         | 5004.                | 533.6                | 42.17         |
|         | 1782.                | 532.3                | 44.67         |
|         | 2273.                | 532.5                | 42.50         |
|         | 3332.                | 533.0                | 42.67         |

PLAN

① ② ③ ④ ⑤

### SECTION 4

| STATION | MAXIMUM<br>FLOW, CFS | MAXIMUM<br>STAGE, FT | TIME<br>HOURS |
|---------|----------------------|----------------------|---------------|
| 304     |                      |                      |               |
|         | 3544.                | 522.2                | 42.83         |
|         | 4795.                | 522.6                | 42.33         |
|         | 1772.                | 521.3                | 44.83         |
|         | 2224.                | 521.6                | 42.67         |
|         | 3228.                | 522.1                | 42.67         |

① ② ③ ④ ⑤

### SECTION 5

| STATION | MAXIMUM<br>FLOW, CFS | MAXIMUM<br>STAGE, FT | TIME<br>HOURS |
|---------|----------------------|----------------------|---------------|
| 405     |                      |                      |               |
|         | 3410.                | 506.9                | 42.83         |
|         | 4196.                | 507.5                | 42.58         |
|         | 1758.                | 505.6                | 45.00         |
|         | 2180.                | 505.9                | 42.83         |
|         | 3151.                | 506.7                | 42.83         |

① ② ③ ④ ⑤

### SECTION 6

| STATION | MAXIMUM<br>FLOW, CFS | MAXIMUM<br>STAGE, FT | TIME<br>HOURS |
|---------|----------------------|----------------------|---------------|
| 506     |                      |                      |               |
|         | 2870.                | 478.0                | 43.17         |
|         | 3140.                | 479.0                | 42.67         |
|         | 1675.                | 478.0                | 45.33         |
|         | 1954.                | 478.2                | 43.33         |
|         | 2688.                | 478.7                | 43.17         |

① ② ③ ④ ⑤

## LIST OF REFERENCES

1. "Recommended Guidelines for Safety Inspection of Dams," prepared by Department of the Army, Office of the Chief of Engineers, Washington, D. C. (Appendix D).
2. "Unit Hydrograph Concepts and Calculations," by Corps of Engineers, Baltimore District (L-519).
3. "Seasonal Variation of Probable Maximum Precipitation East of the 105th Meridian for Areas from 10 to 1,000 Square Miles and Duration of 6, 12, 24, and 48 Hours," Hydrometeorological Report No. 33, prepared by J. T. Riedel, J. F. Appleby and R. W. Schloemer, Hydrologic Service Division Hydrometeorological Section, U. S. Department of the Army, Corps of Engineers, Washington, D. C., April 1956.
4. Design of Small Dams, U. S. Department of the Interior, Bureau of Reclamation, Washington, D. C., 1973.
5. Handbook of Hydraulic, H. W. King and E. F. Brater, McGraw-Hill, Inc., New York, 1963.
6. Standard Handbook for Civil Engineers, F. S. Merritt, McGraw-Hill, Inc., New York, 1968.
7. Open-Channel Hydraulics, V. T. Chow, McGraw-Hill, Inc., New York, 1959.
8. Weir Experiments, Coefficients, and Formulas, R. E. Horton, Water Supply and Irrigation Paper No. 200, Department of the Interior, United States Geological Survey, Washington, D. C., 1907.
9. "Probable Maximum Precipitation Susquehanna River Drainage Above Harrisburg, Pennsylvania," Hydrometeorological Report 40, prepared by H. V. Goodyear and J. T. Riedel, Hydrometeorological Branch Office of Hydrology, U. S. Weather Bureau, U. S. Department of Commerce, Washington, D. C., May 1965.
10. Flood Hydrograph Package (HEC-1) Dam Safety Version, Hydrologic Engineering Center, U. S. Army, Corps of Engineers, Davis, California, July 1978.
11. "Simulation of Flow Through Broad Crest Navigation Dams with Radial Gates," R. W. Schmitt, U. S. Army, Corps of Engineers, Pittsburgh District.


12. "Hydraulics of Bridge Waterways," BPR, 1970, Discharge Coefficient Based on Criteria for Embankment Shaped Weirs, Figure 24, page 46.
13. Applied Hydraulics in Engineering, Morris, Henry M. and Wiggert, James N., Virginia Polytechnic Institute and State University, 2nd Edition, The Ronald Press Company, New York, 1972.
14. Standard Mathematical Tables, 21st Edition, The Chemical Rubber Company, 1973, page 15.
15. Engineering Field Manual, U. S. Department of Agriculture, Soil Conservation Service, 2nd Edition, Washington, D. C. 1969.

**APPENDIX E**


**FIGURES**


## LIST OF FIGURES

| <u>Figure</u> | <u>Description/Title</u>                     |
|---------------|--|
| 1             | Regional Vicinity and Watershed Boundary Map |
| 2             | General Plan, Dams Nos. 1, 2, and 3          |
| 3             | Plan and Cross Section (1925)                |
| 4             | Plan and Cross Section (1938)                |











THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO BOM








# **TYPICAL CROSS SECTION OF BREAST OF DAM NO. 1**


SHOWING LIMITS OF EARTH AND ROCK FILL



HOR. SCALE } 1" = 5'  
VER. SCALE }



**TYPICAL SECTION  
OF  
RUBBLE RETAINING WALL  
LAID WITH 1:3 MORTAR JOINTS  
SCALE 1/2\"/>**

See page 41 This Point to be marked  
when Elevation for this Foundation is Made





THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDG

APPENDIX F

GEOLOGY

### Geology.

Lebanon Reservoir Dam No. 1 is located on the West Branch of Hammer Creek, about 6 miles southeast of the City of Lebanon, at the foot of South Mountain. The dam lies about 9 miles below the source of the West Branch of Hammer Creek, a tributary of Cacalico Creek that empties into Conestogo Creek.

Physiographically, this area is located in the Triassic Lowland Section of the Piedmont Province of eastern Pennsylvania.

Structurally, the major regional feature is a synclinalorium whose longitudinal axis is generally trending northeast-southwest. "The entire south limb of the synclinalorium in the Lebanon Valley appears to be overturned and essentially recumbent." The local structure of the Triassic rocks in the Richland quadrangle can be best described as a broadly warped and block faulted homocline.

"Near the Lebanon Reservoirs, possible faults are associated with the gap in the north border diabase dike." This area lies immediately southwest of the dam as shown on the Geology Map.

The rock strata underlying the dam and reservoir is the Gettysburg Formation, a member of the Newark Group of Triassic age. The Newark Group is a thick sedimentary sequence composed of shales, sandstones, and conglomerates, intruded by thick sills and dikes of diabase. The Gettysburg Formation consists of red shales, quartose red sandstones, and quartz conglomerates.

---

Gray, G., Geyer, A.R., and McLaughlin, D.B., "Geology of the Richland Quadrangle," Atlas 167D, Pennsylvania Geological Survey, Fourth Series, 1958.





## LEGEND

### TRIASSIC

- diabase**  
Medium coarse grained, dark gray, composed chiefly of gray plagioclase feldspar and black or green augite.
- conglomerate**  
Interbedded "shale conglomerate," coarse cobble conglomerate and red sandstone.
- sandstone**  
Fine to coarse, red and brown, quartzose sandstone with a few red shale interbeds.
- limestone + shale conglomerate**  
Fine to coarse, red and brown, quartzose sandstone with thin bands of quartz pebble conglomerate.

GETTYSBURG FM.

### CAMBRIAN

- Buffalo Springs Member**  
Light to pinkish gray limestone, cryptozoon beds near top, sandy in part, fine to coarse crystalline, interbedded dolomite, laminated in part.

### SCALE



Reference:  
Geologic atlas of Pennsylvania,  
Geology of the Richland Quadrangle,  
Pennsylvania Geological Survey,  
Fourth Series, Atlas 167 D, 1936.

### GEOLOGY MAP

**gai**  
CONSULTANTS, INC.